

3-Authorization number PA03213460 Reference no: 68142 Status: Approved Approved by films Approved date 8/8/2022
Billing Address Address VIN Retail sold on

34	 Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDTSGR20P3100447					
Item	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	120242  Stabilizer Jack	0.00	0.50			1	0.50	Complaint:COVER ON FRONT STAB JACK MOTOR NEEDS REPLACED Cause:COVER IS MISSING Correction:NEED TO INSTALL COVER KRV- Missing / incorrect parts need to be noted with KRV to be considered warrantable.
2	310082  Cabinet Door - Re	0.00	0.30	0.10		1	0.20	Complaint:STAPLE HOLES NEED FILLED IN CABINETS UNDER TV Cause:STAPLE HOLES IN CABINETS Correction:FILLED WITH PUTTY KRV – Approved as a Goodwill gesture (non-warranty).
3	230011  Entrance Door - I	0.00	0.30	0.20		1	0.20	Complaint:ENTRY DOOR LATCH NEEDS ADJUSTED Cause:DOOR LATCH NEEDS PUSHED OVER SO DOOR WILL LATCH Correction:TOOK BLOCK AND HAMMER AND PUSHED LATCH OVER. KRV – Labor time approved in accordance with Keystone RV's flat rate manual.
4	120751  Step - Repair	0.00	0.30	0.30		1	0.50	Complaint:ENTRY STEPS ARE HITTING THE DOOR FRAME Cause:steps are hitting door frame. Correction:adjusted brackets that hold the door inside door frame so they wont hit frame.
5	3202008A  Panel - Interior W.	0.00	0.30	0.10		1	0.10	Complaint:GLUE ON WALL PANEL NEXT TO THE FRIDGE Cause:remove glue on wall Correction:removed mineral spirits and rag KRV – Labor time approved in accordance with Keystone RV's flat rate manual.
6	1201925B  Power Jack, Cove	0.00	0.20	0.20		1	0.20	Complaint:GLUE ON TONGUE JACK COVER Cause:glue on tongue jack cover needs removed. Correction:removed with mineral spirits and a rag.

paper claims only use one pre-authorization number per warranty claim for
Please print a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

e-Auth[®]ization

8/10/20
12:35:37 PM

Job Root Job Description of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
3-Authorization	number PA03213460			0.90				

For paper claims **only**, use one pre-authorization number per warranty claim for

multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the