

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 68180
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 10963 - 2023 COUGAR HALF-TON 27SGS 4YDFCGM25PV500817
VIN: 4YDFCGM25PV500817 HIN: SER#: 4YDFCGM25PV500817
Mileage: 0 Work Order Comp: 14 SEP 22
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 04 AUG 22 Inv #: 382612

WO # Job # Description JOB INFORMATION

68180 1 CHECK STOVE NOT INSTALLED RIGHT
Stove top is bent and the front of the stove above where the knobs are located is bent. The stove has also got into the countertop a little bit. Rear post that holds stove top is bent. Rear vent for oven is also bent.
REMOVED THE STOVE TOP AND STRAIGHTENED THE VENTS. ALIGNED THE STOVE TO COUNTER TOP. THEN PUT NEW STOVE TOP ON. CHECKED THE ORIGINAL OVEN DOOR THERE IS NO DAMAGE, SO I DIDNT REPLACE IT. THE KNOB FACE PLATE IS BROKEN TOOK PICTURE. GOT WITH DENNY ABOUT STOVE bring unit in, open up, get parts from parts room, remove range from cabinet, disconeting gas and 12vdc lines, remove screws holding back on, discont gas lines from oven valve, disconet thermal cuppuler from valve, pull back away from oven to get hand down inside of wall to remover thermastat line from oven, put new valve body under old valve body on top of range and start transferring wires from one valve body to the other valve body, 3 of the spark wires the ends broke off befor comming loose from the sparker, find ends and put new ends on wires, run 12vdc test wires to range and test lights and spark, install range in cabinet conet gas line, conet 12vdc lines, turn on gas and test, check for gas leak with gas detition fluid on all contions that was changed, all butners light and all lights liteclean up and put old parts in partsroom, close unit up and pull out

Part No Job# Description PARTS Qty Price Total

677570 1 Range - Top Tray Module Only - 21 1.00 176.13 176.13

Claim : 68180

```

*****
Part No      Job#  Description          PARTS          Qty      Price      Total
*****
686833       1    Range - Oven Door Assembly - 21"  1.00     156.62     156.62
677573       1    Range - Front Panel Module - Blac  1.00     299.37     299.37

```

```

*****
Lab Code     Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990         1    MISCELLANEOUS REPAIR  0.00     150.00      0.00
Z990         1    MISCELLANEOUS REPAIR  0.36     150.00     54.00
Z990         1    MISCELLANEOUS REPAIR  0.64     150.00     96.00
Z990         1    MISCELLANEOUS REPAIR  0.00     150.00      0.00

```

```

*****
Excode      Job#  Description          EXTRAS          Qty      Price      Total
*****
FRT         1    FREIGHT FOR ALL PARTS  1.00     115.41     115.41

```

```

Parts Total:      632.12
Labour Total:     150.00
Sublet Total:       0.00
Extras Total:     115.41

```

>>>> Claim Total: 897.53

Customer Signature: _____

Date: _____