



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68208
Promised Date: 31 AUG 22

CUSTOMER WORK ORDER

WO #: 68208 (Appointment Date: 17 AUG 2022 - Time: 09:30am)

Customer: 51861 - MARSHALL, DANIEL Stock #: 10991

R. - 812-549-5063

Tag:

Author: BJW

Location: 0815 SEE IF BH HAS

AUTHORIZATION FROM RIVERSIDE

Stock Desc: 2022 TT RIVERSIDE RV

RETRO 135

Chassis #: 59CCC1516NL004358

Serial #: 59CCC1516NL004358

Mileage:

Licence:

Invoice #:

Date In: 08 AUG 22

Promised: 31 AUG 22

Date Sched:

Completed: 15 AUG 22

Warr. Date: 18 SEP 21

Job #1 - Warranty

COMPLAINT: CUSTOMER WAS GETTING READY TO LEAVE FOR A CAMPING TRIP SO HE PLUGGED TO SHORE POWER TO GET HIS REFRIGERATOR COLD. IT DID GET COLD, BUT WHEN HE CHECKED IT JUST PRIOR TO LEAVING, HE FOUND THE REFRIGERATOR AND THE FREEZER TO BE WARM.

CORRECTION: BROUGHT CAMPER IN FROM FRONT OF LOT AND PUT IN BAY, HOOKED UP POWER CHECKED VOLTS AT REF WAS OVER 13 AND CHECKED BATTERY WAS ALSO 13 FILLED OUT SHEET FOR WARRENTY, HAD TO TAKE REF OUT TO GET TO SCREWS IN BACK, PUT BACK TOGETHER WAIT FOR WARRENTY. took ref out and found inline fuse, fuse was blown, according to furion i had to cut out old inline fuse and replace with inline spade fuse did that and wired together and hooked everything else back up, ref works letting it run to make sure it gets to temp.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	150.00

Parts

Part #	Description	Qty	Price	Total
19-3535	Fuse Holder; ATO/ ATC Blade Fuses; 5-1/2 Inch 12 Gauge Wire; With Fuse	1.00	3.92	3.92

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 153.92

Parts Total: 3.92
Labour Total: 150.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 153.92

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer #: 51861
MARSHALL, DANIEL R.

