

e-AuthORIZATION

8/17/20

10:18:53

Authorization Number PA03223201 Reference no: 68245 Status: Approved Approved by papca Approved date 8/17/2022
 Address 600 E Baseline Rd Retail sold on
 Evansville, IN 47725 VIN

34 Basden's American RV Basden's American RV 4YDFCGS27N2503252 7/23/2022
 600 E Baseline Rd
 Evansville, IN 47725

Job #	Root Job #	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3201816	Decorative Wood	0.00	0.20	0.10		1	0.10	Complaint:OVERHEAD TRIM ON OBS SLIDE TRIM LOOSE Cause:trim loose on slide out. Correction:secured trim with brad nails. filled staple holes with putty. KRV - REPAIR ONLY approved.
2	3202108	Framed Picture - I	0.00	0.50	0.50		1	0.10	Complaint:2X4 IN BASEMENT AREA BROKEN NEEDS REPLACED Cause:2x4 under bed is split on one side where they secured it into the wall. Correction:removed damaged 2x4 got a new 2x4 and cut to length. drilled pilot holes so i could toe nail it into the wall without splitting. secured to wall secured from top through the plywood under the bed. cleaned up mess. KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
3	6102314B	Fresh Water Tank	0.00	2.00	2.00		1	0.80	Complaint:VENT FOR FRESH TANK NOT WORKING Cause:vent for fresh tank is pinched somewhere in the underbelly. causing water to backfeed through fill hose. Correction:cut open underbelly to access tank fitting. removed fresh water inlet housing removed vent line. removed breaker panel to access hole in floor leading to underbelly. ran new hose through floor. took fish tape and pulled line over to fresh tank. secured line to fresh tank. secured line to vent line on housing. filled fresh tank all the way without water backfeeding. taped underbelly. installed breaker panel. installed fresh inlet housing and sealed with silicone. drained fresh tank KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.

Authorization number PA03223201 2.60

Paper claims only use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the