



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68253
Promised Date: 31 AUG 22

CUSTOMER WORK ORDER

WO #: 68253

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BJW
Location: WELCOME BACK BEN

Stock #: 11244
Stock Desc: 2023 TT RIVERSIDE RV
INTREPID 210
Chassis #: 59CCC2328PL006536
Serial #: 59CCC2328PL006536
Mileage: 0
Licence:

Invoice #:
Date In: 12 AUG 22
Promised: 31 AUG 22
Date Sched:
Completed: 12 SEP 22
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*68406 on 27 AUG 22
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

CAUSE: PDINTT - PDI NEW TRAVEL TRAILER.

CORRECTION: Moved unit into shop from sales lot. Purged and filled LP tanks. Mounted battery box. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Operated all stab jacks. Checked roof and sealed a few screw heads. Checked awning. Checked entrance door and all compartment doors. Checked power cord. Checked all interior lights. Checked converter output. Checked all electrical outlets and GFCI outlets. Checked all cabinets and drawers. Checked all windows and blinds. Applied all company decals. Added water to fresh water tank and flushed water lines. Opened by-pass on water heater and filled. Purged all air from water lines. Checked all water lines and faucets for leaks. Performed LP drop test and set LP pressure at 11 in.wc. Checked TV Antenna and Radio. Used test TV and checked TV Antenna. Recorded all serial numbers and took pictures. Filled all holding tanks and checked monitor panel. Drained all holding tanks, including water heater. Move unit to sales lot.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: SHOWER SURROUND PULLING AWAY. NOTED ON DEL

CAUSE: SHOWER SURROUND PULLING AWAY. NOTED ON DELIVERY.

Customer #: 1000
BASDEN'S AMERICAN RV,



CORRECTION: Shower surround bowed between fasteners. Added more fasteners in bowed areas.
Sealed edge of shower surround with white silicone.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	55.50
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	19.50
Subtotal for Job #1:			75.00

Job #2 - Warranty

COMPLAINT: 4 BLINDS IN SLIDE WILL NOT STAY UP

CAUSE: 4 BLINDS IN SLIDE WILL NOT STAY UP.

CORRECTION: Tightened strings on all window blinds on slideout.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	45.00
Subtotal for Job #2:			45.00

Job #3 - Warranty

COMPLAINT: STAPLE HOLES NEED FILLED IN CABINET UNDER SINK

CAUSE: STAPLE HOLES NEED FILLED IN CABINET UNDER SINK.

CORRECTION: Filled staple holes with matching putty.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	15.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	15.00
Subtotal for Job #3:			30.00

Job #4 - Warranty

COMPLAINT: STAPLE HOLES IN MEDICINE CABINET

CAUSE: STAPLE HOLES IN MEDICINE CABINET.

CORRECTION: Filled all holes in medicine cabinet.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	15.00
Subtotal for Job #4:			15.00

Job #5 - Internal

COMPLAINT: CIRCUIT BREAKERS ON TONGUE IN WAY OF HITCH BRACKETS

CAUSE: CIRCUIT BREAKERS ON TONGUE IN WAY OF HITCH BRACKETS.

CORRECTION: Relocated both battery ground wires. Removed both circuit breakers to relocate. One of the circuit breakers has a broken mounting flange. Replaced broken circuit breaker. Remounted circuit breakers to clear hitch brackets. Removed junction box cover. Made up new longer wire to connect junction box to relocated circuit breaker. Remounted junction box cover. Reconnected battery wire to circuit breaker.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

W/O: 68253
Promised Date: 31 AUG 22



Customer #: 1000
BASDENS AMERICAN RV,



Z990 MISC LABOUR CODE (EXTERNAL) DKM N/C

Parts

Part #	Description	Qty	Price	Total
55-8171	CIRCUIT BREAKER-20A	1.00	N/C	N/C
Subtotal for Job #5:				0.00

Job #6 - Warranty

COMPLAINT: DEAD BOLT WILL NOT LOCK

CAUSE: DEAD BOLT WILL NOT LOCK.

CORRECTION: Door frame material will not dead bolt plunger lock. Cleared out material for plunger to extend and lock.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	30.00
Subtotal for Job #6:			30.00

Job #7 - Warranty

COMPLAINT: BLACK TANK FLUSH HOSE PINCHED FLAT

CAUSE: BLACK TANK FLUSH HOSE PINCHED FLAT.

CORRECTION: Cut pinched section of black tank flush hose out. Installed 90 deg elbow with clamps. Checked for leaks. OK.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	60.00

Parts

Part #	Description	Qty	Price	Total
88-8309	BARB ELBOW 1/2 X 1/2	1.00	0.86	0.86
Subtotal for Job #7:				60.86

Job #8 - Warranty

COMPLAINT: GREY TANK NOT READING CORRECT ON MONITOR

CAUSE: GREY TANK NOT READING CORRECT ON MONITOR PANEL.

CORRECTION: It takes a long time for monitor to show 1/3 and then it jumps to full. Changed wires on grey tank. Moved full wire to extra sensor at top of tank. Grey tank now reads full. Open dupm valve and monitor gradually drops from full to 2/3 to 1/3 to empty. Started filling grey tank again. Monitor will read 1/3 for a long time, Then go to 2\3 and then full. Monitor panel now reading ok. Drains are slow.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	150.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00
Subtotal for Job #8:			150.00

W/O: 68253
Promised Date: 31 AUG 22



Customer #: 1000
BASDEN'S AMERICAN RV,



Parts Total: 0.86
Labour Total: 405.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 405.86

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 12 Sep 2022

W/O: 68253
Promised Date: 31 AUG 22



Customer #: 1000
BASDENS AMERICAN RV,

