



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68270
Promised Date: 30 JUN 22

CUSTOMER WORK ORDER

WO #: 68270

Customer: 41423 - CURL, JEFFREY -
812-306-7594

Tag:

Author: BJW

Location: 0916 BH TO CLOSE

Stock #: 11187

Stock Desc: 2022 5W ALLIANCE RV
VALOR 40V13

Chassis #: 7M5FV4536NA005786

Serial #: 7M5FV4536NA005786

Mileage: 0

Licence:

Invoice #:

Date In: 15 AUG 22

Promised: 30 JUN 22

Date Sched:

Completed: 16 SEP 22

Warr. Date: 18 JUN 22

Job #5 - Warranty

COMPLAINT: THE FRONT MOST SEAT IN THE COUCH THAT IS LOCATED NEAR THE KITCHEN
POPS WHEN IT RECLINES. YOU WILL HAVE TO SET IN THE SEAT TO GET IT TO DUPLICATE.

CAUSE: arms are hitting under the couch as moving foot rest

CORRECTION: SECTIONAL SET IS HITTING ON THE MECHANISMS NOT THE FRAME, TRY TO PUT
WASHERS IN AS LCI SAID, DID NOT FIX, TURN IN PO,
PUT BACK TOGETHER AND IN SLIDEROOM CLOSE UP UNIT AND PULL OUT TO LOT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	75.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	75.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00

Parts

Part #	Description	Qty	Price	Total
18762	RECLINER - RHF (LEFT ARM) - MISTERO PEBBLE - 20202177821&20202182131	1.00	884.99	884.99

Subtotal for Job #5: 1,034.99

Job #6 - Warranty

COMPLAINT: THE TWO WOODED END CAPS ON EACH SIDE OF THE TV ARE LOOSE.

CAUSE: nails no long enuf to go in to wall

CORRECTION: find new unit on lot to figure out where trim block go, they are part of the crown molding use 2
in nails to mount with

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	30.00

Subtotal for Job #6: 30.00

Job #7 - Warranty

COMPLAINT: THE SCREWS ARE BACKING OUT OF THE THREE SEASON DOORS. CUSTOMER HAS
ALSO NOTICED A BLACK GUMMY SUBSTANCE OVER THE DOORS WHICH IS PREVENTING THEM
FROM SLIDING PROPERLY.

CORRECTION: work it to inside release for back ramp outside takes DB key, open ramp and inspect doors,



Customer #: 41423
CURL, JEFFREY

found screws loose have ben over torked, replace # 6 screws with # 8s and test doors

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	45.00
Subtotal for Job #7:			45.00

Job #8 - Internal

COMPLAINT: THE WINDOWS IN THE THREE SEASON DOOR WILL NOT STAY UP.

CAUSE: inspect windows and test

CORRECTION: inspect windows and test

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Subtotal for Job #8:			0.00

Parts Total: 884.99
Labour Total: 225.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 1,109.99

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 16 Sep 2022

W/O: 68270
Promised Date: 30 JUN 22



Customer #: 41423
CURL, JEFFREY

