



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 68287  
Promised Date: 31 AUG 22

### CUSTOMER WORK ORDER

WO #: 68287 (Appointment Date: 16 AUG 2022 - Time: 07:00am)

Customer: 52399 - TOELLE, SCOTT -  
812-483-1767

Stock #: 11140

Stock Desc: 2022 5W KEYSTONE  
COUGAR 316RLS

Chassis #: 4YDFCGR24N2509449

Serial #: 4YDFCGR24N2509449

Mileage:

Licence:

Invoice #:

Date In: 16 AUG 22

Promised: 31 AUG 22

Date Sched:

Completed: 27 AUG 22

Warr. Date: 17 JUN 22

#### Job #1 - Internal

COMPLAINT: REVISIT SHOWER FIX JOB FROM wo#68072. THE FIX HAS COME LOOSE AGAIN

CAUSE: REVISIT SHOWER FIX JOB FROM WO# 68072 THE FIX HAS FCOME LOOSE.

CORRECTION: Moved unit into shop from service lot. Checked top edge of shower surround. Shurround bowed out in two places. Added two plastic rivets to secure tight to wall. Resealed top edge with clear silicone.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

**Subtotal for Job #1: 0.00**

#### Job #2 - Warranty

COMPLAINT: PANELING UNDER FRONT CAP NEAR PIN BOX DROOPING AND HAD HELD WATER. ALSO NEEDS RESEALED ALONG FRONT EDGE.

CAUSE: PANELING UNDER FRONT CAP NEAR PIN BOX DROOPING AND HAD HELD WATER. ALSO NEEDS RESEALED ALONT FRONT EDGE.

CORRECTION: Checked panel under front overhang. Added extra screws and washers to take sag out of panel. Cleaned off old silicone along trim at bottom of front cap. Resealed with new clear silicone on both sides of pin box. Moved unit back to service lot.

#### Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	300.00

**Subtotal for Job #2: 300.00**



Customer #: 52399  
TOELLE, SCOTT



Parts Total: 0.00  
Labour Total: 300.00  
Sublet Total: 0.00  
Extras Total: 0.00  
**WORK ORDER TOTAL: 300.00**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 27 Aug 2022

W/O: 68287  
Promised Date: 31 AUG 22



Customer #: 52399  
TOELLE, SCOTT



Customer Work Order

