·e-Authorization

8/30/20
04:44:46 F

e-Authorization number PA03234362 Reference no: 68290 Status: Approved Approved by papca Approved date 8/29/2022

rvicing aler	Name	Address	VIN	Retail sold on
94	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDTCGM26PL500534	

Ju pe of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	6200206B	LP Bottle - Replac	0.00	0.20	0.20		1	0.20	Complaint:LP TANK WILL NOT FILL Cause:LP TANK WILL NOT FILL UP AT ALL. NEED NEW TANK Correction:GOT NEW LP TANK AND FILLED UP KRV – Labor time approved in accordance with Keystone RV's flat rate manual. VCB: Vendor Charge Back item.
2	3201816A	Decorative Wood	0.00	0.20	0.10		1	0.10	Complaint:BEDROOM SIDE TABLE HAS STAPLE HOLES ON IT\ Cause:BEDROOM SIDE TABLE HAD A ROW OF UNFILLED STAPLE HOLES IN IN Correction:FILLED IN STAPLE HOLES WITH WOOD PUTTY KRV – REPAIR ONLY approved
3	4205516A	Range Hood - Re	0.00	0.20	0.20		1	0.30	Complaint:STOVE LIGHT NOT HOOKED UP RIGHT Cause:STOVE LIGHT WAS NOPT WIRED UP. NEEDS REWIRED Correction:STRIPPED WIRE AND CRIMPED ONJ CONNCTOR AND TESTED KRV – REPAIR ONLY approved.
4	3201816A	Decorative Wood	0.00	0.20	0.10		1	0.10	Complaint:BATHROOM DOOR TRIM NEEDS ADJ Cause:BATHROOM DOOR TRIM NEEDS ADJUSTED IT WAS HITTING THE SIDE TRIM NEEDED TO BE CUT Correction:CUT AND AJUSTED TRIM AND REINSTALLED KRV – REPAIR ONLY approved.
e-Authorization number PA03234362					0.60				

r paper claims only use one pre-authorization number per warranty claim for
aple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the