



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68352
Promised Date: 31 AUG 22

CUSTOMER WORK ORDER

WO #: 68352

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: P.HUNT
Location: 0923 BH TO CLOSE

Stock #: 10800
Stock Desc: 2023 TT ALLIANCE RV
VALOR 31T13
Chassis #: 7M5TV3528PA007059
Serial #: 7M5TV3528PA007059
Mileage: 0
Licence:

Invoice #:
Date In: 22 AUG 22
Promised: 31 AUG 22
Date Sched:
Completed: 28 SEP 22
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*68510 on 09 SEP 22
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

CORRECTION: DID PDI ON UNIT. PUT 5 GALLONS OF GAS WITH STAYBILL IN UNIT TO RUN THE GENERATOR AND RAN IT FOR 10 MIN. EXTENDED THE OUTSIDE LADDER THAT ATTACHES TO SIDE OF CAMPER. TALKED WITH BEN ABOUT ORDERING A TABEL FOR THE BACK STORAGE AREA

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C

Sublet

Description	Total
GAS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

NO TABLE IN BACK ROOM

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: BEDROOM DOOR GUIDE IS BROKEN

CORRECTION: screwed door gide back to the floor

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	15.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #2: 15.00

Job #3 - Warranty

COMPLAINT: LP TANK COVER PUT TOGETHER WITH ZIP TIES

CORRECTION: removed zip strips and replaced with nuts and bolts

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	60.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00

Subtotal for Job #3: 60.00

Job #4 - Warranty

COMPLAINT: THE CORD UNDER THE REFRIGERATOR IS STICKING OUT.

CAUSE: it was the gas line that was showing under the refrigerator when slide room goes in and out.

CORRECTION: i added a small strip of trim behind the trim under the drawer to keep the gas line from sticking out when slide is activated.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	30.00

Subtotal for Job #4: 30.00

Job #5 - Warranty

COMPLAINT: THE BEDROOM DOOR TRIM IS LOOSE.

CAUSE: trim is too long and is bowing in the middle. and not attached

CORRECTION: cut 1/8 of an inch off bottom of trim and glued trim back to wall

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	30.00

Subtotal for Job #5: 30.00

Job #6 - Internal

COMPLAINT: THE BATTERY COMPARTMENT WIRING IS RAT NESTED.

CORRECTION: bill and i had to figure out how the wiring was supposed to be in the battery compartment

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: THE WINDOW BLIND NEXT TO THE COUCH IS NOT HANGING PROPERLY

CORRECTION: the clip that holds the blind in place had came unhooked from the blind on the right side. took valance off and reattached the clip to the blind. reinstalled valance.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	45.00



W/O: 68352
Promised Date: 31 AUG 22



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #7: 45.00

Job #8 - Warranty

COMPLAINT: THE BLIND IN THE STORAGE COMPARTMENT IS FRAYED.

CORRECTION: IT WASNT FRAYED ON THE EDGE IT WAS JUST WRINKLED. I GOT A HAIR DRYER AND SMOOTHED IT OUT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	15.00

Subtotal for Job #8: 15.00

Job #9 - Warranty

COMPLAINT: THERE IS WATER LEAKING FROM UNDER THE TELEVISION STAND

CORRECTION: i had to crimp the fitting to the pex line that ran underneath the tv it was dripping

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	75.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00

Subtotal for Job #9: 75.00

Job #10 - Internal

COMPLAINT: BOTH ENTRY DOOR ARE HARD TO OPEN.

CORRECTION: ADJUSTED BOTH STRIKE PLATES AND SCREEN DOORS ON ENTRY DOORS. THE BOTH WORK SMOOTH.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C

Subtotal for Job #10: 0.00

Parts Total:	0.00
Labour Total:	270.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	270.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 28 Sep 2022

