

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 68366
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11239 - 2023 COUGAR HALF-TON 25RDS 4YDTCGM27PL500512
VIN: 4YDTCGM27PL500512 HIN: SER#: 4YDTCGM27PL500512
Mileage: 0 Work Order Comp: 29 AUG 22
Auth. No: Dealer #: 1194
Warr. Date: 25 AUG 22 Work Order Date: 23 AUG 22 Inv #: 381893

WO #	Job #	Description	JOB INFORMATION
68366	1	WATER LEAKING IN FRONT CAP WINDOW WATER LEAKING IN FRONT CAP WINDOW. Rubber seal around window in front cap has a small gap allowing water to get in and drip on mattress in front bedroom. Pulled rubber seal off across top and around both top corners. Sealed gap across top of window with cvlear silicone. Replaced rubber seal. Taped Next to rubber seal at top and around both top corners. Added clear silicone and removed tape from top of window and top corners.	

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISCELLANEOUS REPAIR		0.50	150.00	75.00
Parts Total:						0.00
Labour Total:						75.00
Sublet Total:						0.00
Extras Total:						0.00
>>>> Claim Total:						75.00

Customer Signature: _____

Date: _____