

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1213087
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2FEXB8NW021807
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$150.00	SITE/WAREHOUSE	320 / 320
OWNER INFORMATION		ITEM #	FET321FEDSLE-320
GARY SCHULTZ		DEALER RO #	68393
8821 GRANT LANE		CLAIM START DATE	08/30/2022
Bridgeport, IL 62417		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	03/07/2022	WARRANTY EXPIRATION DATE	03/07/2023

Claim Line Details

Labor

Line# 1	Operation Code RC-026-01-00-004186	Operational Description 22V243, 2022-181 - FLEXTech QUICK DISCONNECTS - REMEDY (INCLUDES INSPECTION) - Recall/LP Gas System/Replace/No Tread Code
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-08-30 13:53:24 :: RECALL 22V243 LP QUICK CONNECT took pictures and replaced lp quick connect.		
Model #	Dlr Sub Hrs	0.30
Serial #	Appr Hrs	0.30
	Sub Labor Amt	\$45.00
	Appr Labor Amt	\$45.00
Notes		

Labor

Line# 2	Operation Code 40-196-24-11-001297	Operational Description Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-08-30 13:54:31 :: THE BEDROOM SLIDE ONLY CLICKS WHEN TRYING TO RUN IT OUT. IT WILL NOT GO OUT. checked switch and board and all had power,checked in bedroom and found underneath bed circuit board was unplugged,crimped wire on and plugged in and it works all is good.		
Model #	Dlr Sub Hrs	0.30
Serial #	Appr Hrs	0.30
	Sub Labor Amt	\$45.00
	Appr Labor Amt	\$45.00
Notes		

Submitted	Labor Amt	\$90.00	Approved	Labor Amt	\$90.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$90.00		Total	\$90.00

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.