



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68409

CUSTOMER WORK ORDER

WO #: 68409

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0902 CHECK WORK

Stock #: 11248
Stock Desc: 2023 5W KEYSTONE
COUGAR HALF-TON 25RES
Chassis #: 4YDFCGL27PV501663
Serial #: 4YDFCGL27PV501663
Mileage: 0
Licence:

Invoice #:
Date In: 29 AUG 22
Promised:
Date Sched:
Completed: 31 AUG 22
Warr. Date:

Job #PDINFW - Internal

Transferred to BAS*68456 on 01 SEP 22
Estimate amount was 0.00
PDI - NEW FIFTH WHEEL

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #1 - Internal

COMPLAINT: Transferred to BAS*68456 on 01 SEP 22
Estimate amount was 0.00
SEWER CAPS MISSING ON TUBE - PER DREW

CORRECTION: BH GAVE TO DREW

Other Services

Code	Description	Qty	Price	Total
FRT	UPS- SEWER CAPS	0.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: SHOWER SIDE NEED SEALED

CAUSE: SHOWER SIDE NEEDS SEALED UP

CORRECTION: SEALED UP SHOWER SIDE

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	45.00



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #2: 45.00

Job #3 - Internal

COMPLAINT: WATER HEATER DOOR NEED ADJED

CAUSE: WATER HEATER DOOR WOULDNT LATCH PROPERLY DUE TO LATCHING MECHNISIM
NEEDING ADJUSTING

CORRECTION: ADJUSTED WATERHEAR DOOR LOCKING MECHANSIM

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	N/C
Subtotal for Job #3:			0.00

Job #4 - Warranty

COMPLAINT: BEDROOM CABINET HAS TAPE PEALING

CAUSE: BEDROOM CABNIET TAPE PEELING

CORRECTION: FIXED TAPE

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	15.00
Subtotal for Job #4:			15.00

Job #5 - Warranty

COMPLAINT: BATHROOM SINK NEEDS TO BE SEALED

CAUSE: BATHROOM SINK NEEDS SEALED UP

CORRECTION: SEALED UP BATHROOM SINK

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	45.00
Subtotal for Job #5:			45.00

Parts Total: 0.00
Labour Total: 105.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 105.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 02 Sep 2022

Customer #: 1000
BASDEN'S AMERICAN RV,

