

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 68465  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725

Phone:

Stock Number: 11251 - 2023 CATALINA 243RBSLE 5ZT2CANB8PU041140

VIN: 5ZT2CANB8PU041140 HIN:

SER#: 5ZT2CANB8PU041140

Mileage: 0

Work Order Comp: 20 OCT 22

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 02 SEP 22

Inv #: 384239

\*\*\*\*\*  
WO #      Job #      Description      JOB INFORMATION  
\*\*\*\*\*  
68465      1      WHEN UNIT WAS DELIVERED THE STOVE FELL OUT AND IS ON THE FLOOR  
DOOR THAT WAS SENT IS WRONG. THE DOOR WE NEED IS STAINLESS.  
PULLED UNIT INTO SHOP. REMOVED DAMAGED DOOR. INSTALLED NEW DOOR.  
HOOKED UP WIRES AND GAS LINE. SECURED STOVE TO COUNTER. CLEANED  
GLASS OUT OF INSIDE. CLEANED UP MESS.  
  
68465      2      THE WOODEN STILES ARE DAMAGED UNDER THE STOVE.  
  
68465      8      THE STAPLES ABOVE THE SLIDE OUT ARE EXPOSED.  
  
68465      3      THE TRIM ON THE SLIDE OUT ROOM IS LOOSE  
TRIM WAS LOOSE ON SLIDE OUT CEILING  
SECURED TRIM WITH BRAD NAILS  
  
68465      4      THE ENTRY DOOR HITS THE DOOR FRAME WHEN OPENING AND CLOSING  
entry door hits the latch when trying to open and shut.  
took hammer and a block of wood and moved latch away from door.  
  
68465      5      THE WINDOW GLAZING IS COMING OUT OF THE SLIDE OUT WINDOW.  
WINDOW GLAZING ON BOTTOM CORNER OF SLIDE OUT WINDOW CAME LOOSE  
PUSHED GLAZING BACK ONTO WINDOW FRAME  
  
68465      6      THERE ARE STAINS ON THE COUCH.  
STAINS ON COUCH  
REMOVED STAINS WITH MINERAL SPIRITS AND A RAG

Claim : 68465

\*\*\*\*\*  
 WO #      Job #      Description      JOB INFORMATION  
 \*\*\*\*\*  
 68465      7      THE SHOWER SURROUND NEEDS TO BE SEALED  
                  SHOWER SURROUND IS LEAKING IN CORNERS WHEN TESTING SHOWER.  
                  SEALED INSIDE CORNERS WITH SILICONE.  
  
 68465      9      THE SHOWER FAUCET IS NOT SEALED  
                  shower faucet is not sealed.  
                  applied silicone to shower faucet as needed.

\*\*\*\*\*  
 Part No      Job#      Description      PARTS      Qty      Price      Total  
 \*\*\*\*\*  
 USERRV17D      1      RV17D-OVEN DOOR FOR CF-17 DIGITAL      1.00      72.34      72.34  
 F100285185      2      STILE, LC 18MM" X 2" X 8' SQUARE      8.00      0.95      7.60  
 F100285188      2      3" CABINET STILE      8.00      1.38      11.04  
 500627      8      CLEAR SIKASIL PLUS      2.00      17.86      35.72  
 C01216920      8      PUTTY TAPE - ROLL      1.00      7.12      7.12  
 20-6963      8      Insert Molding Trim Type; 1-1/4 I      1.00      37.94      37.94  
 5460      8      BLACK PUTTY TAPE 1" x 20'      1.00      6.27      6.27  
 5981      8      Trim - Screw Cover - 76 - Narrow      1.00      1.62      1.62

\*\*\*\*\*  
 Lab Code      Job#      Description      LABOUR      Hrs      Rate      Total  
 \*\*\*\*\*  
 Z990      1      MISC LABOUR CODE (EXTERNAL)      0.00      150.00      0.00  
 Z990      1      MISC LABOUR CODE (EXTERNAL)      0.00      150.00      0.00  
 Z990      1      MISC LABOUR CODE (EXTERNAL)      1.00      150.00      150.00  
 Z990      1      MISC LABOUR CODE (EXTERNAL)      0.00      150.00      0.00  
 Z990      2      MISC LABOUR CODE (EXTERNAL)      2.00      150.00      300.00  
 Z990      8      MISC LABOUR CODE (EXTERNAL)      1.00      150.00      150.00  
 Z990      3      MISC LABOUR CODE (EXTERNAL)      0.10      150.00      15.00  
 Z990      4      MISC LABOUR CODE (EXTERNAL)      0.10      150.00      15.00  
 Z990      5      MISC LABOUR CODE (EXTERNAL)      0.20      150.00      30.00  
 Z990      6      MISC LABOUR CODE (EXTERNAL)      0.10      150.00      15.00  
 Z990      7      MISC LABOUR CODE (EXTERNAL)      0.30      150.00      45.00  
 Z990      9      MISC LABOUR CODE (EXTERNAL)      0.20      150.00      30.00

\*\*\*\*\*  
 Excode      Job#      Description      EXTRAS      Qty      Price      Total  
 \*\*\*\*\*  
 FRT      1      UPS-OVEN DOOR      1.00      16.63      16.63  
 FRT      2      UPS - STILES      1.00      154.34      154.34

Parts Total:      179.65  
 Labour Total:      750.00  
 Sublet Total:      0.00  
 Extras Total:      170.97

&gt;&gt;&gt;&gt; Claim Total: 1,100.62

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_