



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68517
Promised Date: 30 SEP 22

CUSTOMER WORK ORDER

WO #: 68517

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: DH
Location: 0920 LET BH KNOW THAT
KEYSTONE DENIED

Stock #: 11145
Stock Desc: 2023 TT KEYSTONE
COUGAR HALF-TON 33RLI
Chassis #: 4YDTCGR21PV501653
Serial #: 4YDTCGR21PV501653
Mileage: 0
Licence:

Invoice #:
Date In: 12 SEP 22
Promised: 30 SEP 22
Date Sched:
Completed: 22 SEP 22
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDINTT - PDI NEW TRAVEL TRAILER.

CORRECTION: Moved unit into shop from sales lot. Filled LP tanks. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 80 psi. Checked entrance door and all compartment doors. Checked both awnings and roof. Checked auto leveling jacks and reset. Checked all interior lights. Checked all windows and blinds. Checked all cabinets and drawers. Removed all shipping tape from Refrig, MicroWave and TV. Checked all electrical outlets and GFCI outlets. Checked all solar outlets. Checked all USB outlets. Added water to fresh water tank. Flushed antifreeze from water lines and faucets. Checked all faucets and water lines for leaks. Filled all holding tanks and checked monitor panel. Performed LP drop test and set LP pressure at 11 in.wc. Operated all appliances. Checked TV Antenna, TV, Radio/DVD/CD Player and Fireplace. Applied all company decals. Dumped all holding tanks. Recorded all serial numbers and took pictures. Moved unit to sales lot.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	12.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: HOLE IN FLOOR FOR WATER & WIRING BY
WATER PUMP.

CAUSE: HOLE IN FLOOR FOR WATER & WIRING BY WATER PUMP.

CORRECTION: Open hole in sub floor for water lines, fill hose and electric cables. Taped holes from bottom. Added foam to seal from top. Made panel to cover area on outside.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	75.00
Z990	MISCELLANEOUS REPAIR	DKM	75.00

Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #1: 150.00

Parts Total: 0.00

Labour Total: 150.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 150.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 22 Sep 2022

W/O: 617
Promise Date: 30 SEP 22



Customer #: 1000
BASDENS AMERICAN RV,

