

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 68539
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 46875 - CHUBBY CHOW FACTORY LLC
Address: PO BOX 3641 EVANSVILLE, IN

47735

Phone: 812-455-2400

Stock Number: 2207R - 2022 SPRINGDALE 260BH 4YDTSGL28N3108527

VIN: 4YDTSGL28N3108527 HIN: SER#: 4YDTSGL28N3108527

Mileage: 0

Work Order Comp: 05 OCT 22

Auth. No:

Dealer #: 1194

Warr. Date:

Work Order Date: 13 SEP 22

Inv #: 383541

WO # Job # Description JOB INFORMATION

68539 1 BLACK TANK FLUSH LEAKING WHEN USING
BLACK TANK SLUSH LEAKING AT TANK. THE INLET IS CRACKED NEEDS NEW
TANK
GOT PART FROM PARTS ROOM AND TOOK OUT OF BOX AND FOUND NO TANK
FLUSH IN TANK GOT WITH CRAIG AND GOT ONE OFF OF SHELF TO
INSTALL, TOOK OUT TOILET AND FLANGE IN TANK, TOOK OFF SENSORS ON
TANK, TOOK OFF VALVE AND LINE STRAP AND 2 STRAPS AROUND TANK, TOOK
OFF LINE TO TANK FOR FLUSH, TOOK OFF BAR THAT HOLDS TANK IN TO
REMOVE TANK. ALSO HAD TO PULL VENT ON ROOF AND PULL PVC OUT OF
TANK TO GET DOWN. MEASURED AND CUT HOLE FOR TOILET, MEASURED AND
CUT HOLE FOR VENT PIPE, MEASURED AND CUT HOLE FOR BLACK
FLUSH. INSTALLED TANK IN PLACE AND INSERTED VENT PIPE IN
TANK, INSTALLED VENT COVER BACK ON ON ROOF, INSTALLED TANK SENSOR
WIRES TO TANK AND STRAPED THE STRAPS BACK ON TANK, INSTALLED BLACK
TANK FLUSH HAD TO DRILL 3 SCREW HOLES AND SEAL, HAD TO MAKE NEW
LINE FOR BLACK FLUSH FOR IT TO WORK, INSTALLED DRAIN LINE AND
VALVE AND STRAP TO BLACK TANK AND SEALED DRAIN LINE IN
TANK. INSTALLED PIPE IN TANK FOR TOILET AND SCREW DOWN
FLANGE, INSTALLED TOILET AND WATER LINE, TESTED AND IT DONT LEAK.

Part No Job# Description PARTS Qty Price Total

479190 1 Tank - Holding - 22" x 54" x 8" - 1.00 129.20 129.20
89-8444 1 QUICKIE FLUSH 1.00 31.14 31.14
72-0818 1 1/2" MPT TO 1/2" PEX 1.00 3.81 3.81

Claim : 68539

 Part No Job# Description PARTS Qty Price Total

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISCELLANEOUS REPAIR 0.50 150.00 75.00
 Z990 1 MISCELLANEOUS REPAIR 0.50 150.00 75.00
 Z990 1 MISCELLANEOUS REPAIR 0.00 150.00 0.00
 Z990 1 MISCELLANEOUS REPAIR 3.00 150.00 450.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 1 UPS- TANK 1.00 91.26 91.26

Parts Total: 164.15
 Labour Total: 600.00
 Sublet Total: 0.00
 Extras Total: 91.26

>>>> Claim Total: 855.41

Customer Signature: _____

Date: _____