

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 68543
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 11706 - MICHAEL SHAW
Address: 847 CLEARVIEW AVE. JASPER, IN

47546

Phone: 812-630-8814

Stock Number: 11211 - 2022 MONTANA 3791RD 4YDFM0T24N4703710

VIN: 4YDFM0T24N4703710 HIN:

SER#: 4YDFM0T24N4703710

Mileage: 0

Work Order Comp: 22 SEP 22

Auth. No:

Dealer #: 1194

Warr. Date: 25 JUN 22

Work Order Date: 13 SEP 22

Inv #: 382935

WO # Job # Description JOB INFORMATION

68543 1 KITCHEN WINDOW LEAKING OFF DOOR SIDE
WINDOW LEAKING AT FRONT CORNER.
APPLIED SILICONE, TO OUTSIDE TOP AND CORNERS OF WINDOW. PARKED
UNIT AND LET DRY. PULLED UNIT BACK UP TO SHOP AND WATER TESTED
AGAIN. SMALL LEAK STILL IN TOP CORNER. APLLIED MORE SILICONE.
PARKED AND LET DRY. PULLED UNIT UP TO SHOP AGAINM AND WATER
TESTED. HAD BEN HOFFMAN COME AND VERIFY THAT LEAK WAS FIXED.
CLEANED UP WINDOW. PARKED UNIT.

Lab Code Job# Description LABOUR Hrs Rate Total

Z990	1	MISC LABOUR CODE (EXTERNAL)	0.00	150.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)	0.50	150.00	75.00
Z990	1	MISC LABOUR CODE (EXTERNAL)	0.50	150.00	75.00
Z990	1	MISC LABOUR CODE (EXTERNAL)	0.00	150.00	0.00

Excode Job# Description EXTRAS Qty Price Total

SS	1	SHOP SUPPLIES	1.00	0.00	0.00
----	---	---------------	------	------	------

Parts Total: 0.00

Labour Total: 150.00

Sublet Total: 0.00

Extras Total: 0.00

>>>> Claim Total: 150.00

Customer Signature: _____

Date: _____