

Approved date 9/20/2022

4YDFM0T24N4703710 6/26/2022

Complaint:KITCHEN WINDOW LEAKING OFF DOOR SIDE
Cause:KITCHEN WINDOW LEAKING OFF DOOR SIDE
Correction:APPLIED SILICONE, TO OUTSIDE TOP AND
CORNERS OF WINDOW. PARKED UNIT AND LET DRY.
PULLED UNIT BACK UP TO SHOP AND WATER TESTED
AGAIN. SMALL LEAK STILL IN TOP CORNER. APPLIED MORE
SILICONE. PARKED AND LET DRY. PULLED UNIT UP TO
SHOP AGAIN AND WATER TESTED. HAD BEN COME AND
VERIFY THAT LEAK WAS FIXED. CLEANED UP WINDOW.
PARKED UNIT.

1.00

For paper claims only, use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the