



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68547

CUSTOMER WORK ORDER

WO #: 68547

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: 0926 CHECK PREAUTH

Stock #: 11148

Stock Desc: 2023 5W KEYSTONE

COUGAR 368MBI

Chassis #: 4YDFCGS2XP2501577

Serial #: 4YDFCGS2XP2501577

Mileage: 0

Licence:

Invoice #:

Date In: 13 SEP 22

Promised:

Date Sched:

Completed: 22 SEP 22

Warr. Date:

Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL

CORRECTION: pdi done, did everything on sheet and found other things wrong and fixed in other jobs written.

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
4351	QUICK ROOF EXTREME - BLACK FOR RV'S 4INX25FT	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	12.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #1 - Warranty

COMPLAINT: CHECK BRAKES NOT WORKING WHEN TRAVELING HERE WITH IT

CORRECTION: CHECKED WIRES AT FRONT DRIVER SIDE IN UNDERBELLY AND FOUND WIRES CAME APART, PUT 3 WIRES BACK TOGETHER AND CRIMPED, TAPED UP UNDERBELLY AND THEY WORK FINE NOW.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	75.00

Subtotal for Job #1: 75.00

Job #2 - Warranty

COMPLAINT: FRIDGE DOOR WILL NOT OPEN ALL THE WAY

CORRECTION: TOOK BOTTOM OF BRACKET ON REF AND TOOK OUT SCREWS AND MOVED REF OVER SO DOOR WOULD NOT HIT WALL, SECURED REF BACK IN PLACE.

Labor



Customer #: 1000
BASDEN'S AMERICAN RV,

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	60.00

Subtotal for Job #2: 60.00

Job #3 - Warranty

COMPLAINT: SHOWER DRAIN IS LEAKING

CORRECTION: TOOK DRAIN PIPE OFF AND SCREWED IT BACK ON STRAIGHT AND BOTTOM PIPE AND TESTED AND IT IS GOOD.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	45.00

Subtotal for Job #3: 45.00

Job #4 - Warranty

COMPLAINT: BATHROOM DOOR SHOWER HOLDER WILL NOT STAY IN TRACK

CORRECTION: MOVED HOLDER SO DOOR WOULD NOT COME OUT.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	30.00

Subtotal for Job #4: 30.00

Job #5 - Warranty

BLIND NEXT TO RECLINER IS BROKEN

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	30.00

Parts

Part #	Description	Qty	Price	Total
693186	Shade - Roller - Night Only - 26" x 37" - Value Line - 3 Ply - Bamboo Black - w/Reflective Backing	1.00	39.01	39.01

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	12.38	12.38

Subtotal for Job #5: 81.39

Job #6 - Warranty

COMPLAINT: BLACK TANK FLUSH NOT HOOKED UP

CORRECTION: CLEANED UP WATER AND FOUND THE LINES THAT WERE NOT HOOKED UP, HOOKED UP LINES AND CLAMPED IT AND IT TESTED FINE.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	45.00

Subtotal for Job #6: 45.00



Customer #: 1000
BASDEN'S AMERICAN RV,



Parts Total:	39.01
Labour Total:	285.00
Sublet Total:	0.00
Extras Total:	12.38
WORK ORDER TOTAL:	336.39

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 22 Sep 2022



Customer #: 1000
BASDEN'S AMERICAN RV,

