



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68563
Promised Date: 23 SEP 22

CUSTOMER WORK ORDER

WO #: 68563

Customer: 53058 - STONE, DANIEL G. -
812-830-0647

Tag:

Author: BH

Location: 0928 CHECK PREAUTH

Stock #: 10915

Stock Desc: 2022 TT FOREST RIVER

CHEROKEE GREY WOLF 22MKSE

Chassis #: 5ZT2CKLB3NF002465

Serial #: 5ZT2CKLB3NF002465

Mileage:

Licence:

Invoice #:

Date In: 15 SEP 22

Promised: 23 SEP 22

Date Sched:

Completed: 27 SEP 22

Warr. Date: 23 SEP 22

Job #FPDINTT - Internal

FINAL PDI ON NEW TRAVEL TRAILERS

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Subtotal for Job #FPDINTT: 0.00

Job #E2 - Internal

10K E2 EQUALIZER HITCH

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C

Subtotal for Job #E2: 0.00

Job #BCWT - Internal

BRAKE CONTROL & WIRING - PICKUP TRUCK ONLY

Labor

Code	Description	Mechanic	Total
BCWT	BRAKE CONTROL & WIRING - PICKUP	GAH	N/C
BCWT	BRAKE CONTROL & WIRING - PICKUP	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
3024-P	3024-P BRAKE CONTROL HARNESS	1.00	N/C	N/C
	13-C DODGE			
14-1015	8508220 BRAKE-EVN BRAKE CONTROLLER	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C



Customer #: 53058
STONE, DANIEL G.



Subtotal for Job #BCWT: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT

Parts

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00

Job #WALK - Internal

WALK THRU

Estimated Amount: 180.00

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	VV	N/C

Subtotal for Job #WALK: 0.00

Job #1 - Warranty

COMPLAINT: ALL OF THE CLEARANCE LIGHTS COME ON WHEN THE LEFT TURN SIGNAL IS TURNED ON.

CAUSE: ALL THE CLEARANCE LIGHTS COME ON WHEN THE LEFT IS TURN ON.

CORRECTION: Removed cover on 7 way junction box. Checked all wires connections. All correct and tight. Replace cover. Removed left rear tail cover. Checked bulb. OK. Removed tail light assembly from mounting. Pulled all wires out of hole. Found that ground wire from light was going to the tail light connector. The black wire from the tail light was going to the ground connector. Checked operation of lights. All OK. Remounted tail light and resealed.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	105.00

Subtotal for Job #1: 105.00

Job #2 - Warranty

COMPLAINT: BRAKE AWAY SWITCH IS FALLING APART

CAUSE: BRAKE AWAY SWITCH IS FALLING APART.

CORRECTION: Brake away switch fell apart when cord was pulled. Removed damaged switch. Mounted new switch and connected brake wires. Checked operation of new switch. OK.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	60.00

Parts

Part #	Description	Qty	Price	Total
80-00-2060	Trailer Breakaway System Switch; Zip; With 6 Foot Cable And Switch	1.00	16.63	16.63

Subtotal for Job #2: 76.63

Job #3 - Warranty

COMPLAINT: WATER LEAKING IN REAR COMPARTMENT AND OUT OF UNDERBELLY

CAUSE: WATER LEAKING IN REAR COMPARTMENT AND OUT OF UNDERBELLY.

CORRECTION: Removed shower faucet from shower wall. Found hot side of faucet leaking when connected to city water or water pump was turned on. Faucet did not have to be "ON". Removed both



water lines from back of faucet. Replaced both cone washers and reconnected water lines to back of faucet. Checked for water leaks at both connections. No leaks at this time. Remounted faucet to shower wall. Resealed around faucet housing. Checked underbelly below leak. Underbelly full of water. Cut out rear section of underbelly material. This area does not have insulation. Mounted underbelly hard material and secured to wood stringers. Sealed edges with black tape.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	120.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	120.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	210.00

Parts

Part #	Description	Qty	Price	Total
10-7150	CONE WASHER SWIVEL SEAL	2.00	0.30	0.60

Subtotal for Job #3: 450.60

Parts Total: 17.23
Labour Total: 615.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 632.23

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 27 Sep 2022

W/O: 68563
Promised Date: 23 SEP 22



Customer #: 53058
STONE, DANIEL G.

