



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68565
Promised Date: 30 SEP 22

CUSTOMER WORK ORDER

WO #: 68565

Customer: 46875 - CHUBBY CHOW
FACTORY LLC - 812-455-2400

Tag:

Author: BH

Location: 0923 BH TO CLOSE

Stock #: 2102R

Stock Desc: 2022 TT KEYSTONE

SPRINGDALE 1800BH

Chassis #: 4YDTSGG17NW105019

Serial #: 4YDTSGG17NW105019

Mileage:

Licence:

Invoice #:

Date In: 15 SEP 22

Promised: 30 SEP 22

Date Sched:

Completed: 23 SEP 22

Warr. Date:

Job #1 - Warranty

COMPLAINT: BLACK SEWER VALVE IS LEAKING

CORRECTION: small drip at black water valve. i tightened up the 4 bolts and ran water through for 20 minutes and there was no sign of leak.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DWW	0.00
Z990	MISCELLANEOUS REPAIR	DWW	0.00
Z990	MISCELLANEOUS REPAIR	DWW	60.00

Subtotal for Job #1: 60.00

Job #2 - Warranty

COMPLAINT: GFCI NEAR QUEEN BED IS TRIPPING
RANDOMLY. WASH BAY HAD IT HAPPEN WITH
A/C RUNNING, FAN PLUGGED INTO OUTLET
AND TRYING TO RUN AWNING OUT.

CORRECTION: i had the a/c and air mover fan on for 4 hours and the gfci never tripped. i checked voltage on outlets and they all read normal. i also ran out the awning out like wash bay said but it runs on 12 volt. and repaired blind in bunkhouse. the screw had pulled out of the wall. changed the gfci outlet next to the bed

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DWW	0.00
Z990	MISCELLANEOUS REPAIR	DWW	0.00
Z990	MISCELLANEOUS REPAIR	DWW	75.00

Parts

Part #	Description	Qty	Price	Total
72-7218	GFI RECEPTACLE - BLACK	1.00	20.00	20.00

Subtotal for Job #2: 95.00

Customer #: 46875
CHUBBY CHOW FACTORY



W/O: 68-35
Promise Date: 30 SEP 22

Parts Total:	20.00
Labour Total:	135.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	155.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Sep 2022



Customer #: 46875
CHUBBY CHOW FACTORY

