

e-Authorization

10/26/20
06:54:16

3-Authorization number PA03252177 Reference no: 68572 Status: Approved Approved by flamc Approved date 9/21/2022
 Pricing Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDT28025M3112754 9/25/2021
 600 E Baseline Rd
 Evansville, IN 47725

Item	Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2106008B	Slide Out Box - In	0.00	3.00	2.00		1	1.00	Complaint:WALL ON THE SLIDEOUT LOOKS LIKE IT IS MELTING LEFT SIDE Cause:THERE IS A COUCH IN THE WAY THAT NEEDS TO BE MOVED Correction:NEED TO REPLACE THE WALL PANEL INSIDE THE SLIDE ROOM
2	2300118A	Entrance Door - In	0.00	1.50	1.00		1	0.20	Complaint:GAP AT THE TOP OF THE ENTRY DOOR ON BACK DOOR. IT IS LETTING WATER IN Cause:ENTRY DOOR IS BOWED AND NEEDS REPLACED Correction:NEED TO REPLACE ENTRY DOOR KRV - goodwill auth to recamber entry door only. Instructions to recamber available in KeyExpress under manuals, vendor manuals, door, :o[[er=Adkistomg Rv entru dppr camber

3-Authorization number PA03252177
 3.00

paper claims ~~only~~ use one pre-authorization number per warranty claim for
 a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the