

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	CLAIM STATUS Authorized CLAIM 1247935 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CKEC5NY020265 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 017 / 017D ITEM # CKTR16FQ-D DEALER RO # 68610 CLAIM START DATE 09/22/2022 CLAIM END DATE 01/01/1900	
Labor rate: \$150.00 OWNER INFORMATION CHARLES SALA 5311 JONA GOLD CT Evansville, IN 47711 USA		
Retail Date of Purchase 09/28/2021	WARRANTY EXPIRATION DATE 09/28/2022	

Claim Line Details

Labor					
Line# 1	Operation Code	Operational Description			
	60-139-01-00-001542	Single Handle Kitchen Faucet - Plumbing/Kitchen (Galley) Sink/Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2022-09-22 14:08:55 :: KITCHEN FAUCET HAS A DRIP, DOES NOT FULLY SHUT OFF kitchen FAUCET is dripping when you shut off. has a bad seal. had dave look at it with me there is no way to replace seal its sealed up where you cant replace it. needs new kitchEn FAUCET				
	Model #	Dlr Sub Hrs	0.50	Sub Labor Amt	\$75.00
	Serial #	Appr Hrs	0.50	Appr Labor Amt	\$75.00
	Notes				
	Authorized				
Labor					
Line# 2	Operation Code	Operational Description			
	RC-026-01-00-004186	22V243, 2022-181 - FLEXTech QUICK DISCONNECTS - REMEDY (INCLUDES INSPECTION) - Recall/LP Gas System/Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2022-09-22 14:22:55 :: RECALL 22V243 LP QUICK CONNECRET RECALL ON LP QUICK DISCONNECT NEEDS REPLACED REPLACED ON LP QUICK DISCONNECT AND TESTED				
	Model #	Dlr Sub Hrs	0.30	Sub Labor Amt	\$45.00
	Serial #	Appr Hrs	0.30	Appr Labor Amt	\$45.00
	Notes				

Submitted	Labor Amt	\$120.00	Approved	Labor Amt	\$120.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$120.00		Total	\$120.00

DEALER _____ DATE _____ SIGNATURE _____ I certify that I have performed these repairs consistent with Forest River Policies.	CUSTOMER _____ DATE _____ SIGNATURE _____ All repairs described have been inspected and are satisfactory.
---	--