

e-Authorization

3-Authorization number PA03261179 Reference no: 68620 Status: Approved Approved by samya 9/27/2022
 Billing Name Address Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDFCGN29N2501028 10/23/2021
 600 E Baseline Rd
 Evansville, IN 47725

Qty	Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	5100706B	Breaker, 120V - R	0.00	0.40	0.20		1	0.20	Complaint: CONVERTER NOT CHARGING WHEN PLUGGED IN, CUSTOMER HAS TO RUN BATTERY CHARGE ON BATTERY TO FINISH OUT TRIP. Cause: CONVERTER NOT CHARGING WHEN PLUGGED IN, CUSTOMER HAS TO RUN BATTERY CHARGE ON BATTERY TO FINISH OUT TRIP. Correction: Moved unit into shop from front lot. Checked converter breaker at fuse panel. Power cord is not plugged into outlet. Converter breaker was tripped. Reset breaker. Would not stay "ON". Lever is loose and just falls to "OFF" Position. Removed breaker panel front cover. Plugged power cord in and checked converter output while holding breaker "ON". Converter still not charging. Turned in parts request for a new 20 amp breaker. Removed old converter breaker and installed a new 20A breaker. Converter new charging battery at 13.58 volts. Remounted breaker panel front cover.
2	3201408B	Door - Interior Slit	0.00	0.20	0.10		1	0.10	Complaint: THE PLASTIC DOOR KEEPER ON THE BATHROOM DOOR IS BROKEN. Cause: FOUND LATCH IS BROKEN Correction: Installed a sliding patio door lock on wall and door.
3-Authorization number PA03261179					0.30				KRV - Approved as a Goodwill gesture (non-warranty).

paper claims ~~only~~ use one pre-authorization number per warranty claim for
 please a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the