



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68630
Promised Date: 29 OCT 22

CUSTOMER WORK ORDER

WO #: 68630

Customer: 1000 - BASDEN'S AMERICAN

RV -

Tag:

Author: BH

Location: 0930 BH TO CLOSE WO

Stock #: 11146

Stock Desc: 2023 TT KEYSTONE

COUGAR HALF-TON 26RBS

Chassis #: 4YDTCGM21PL500604

Serial #: 4YDTCGM21PL500604

Mileage: 0

Licence:

Invoice #:

Date In: 23 SEP 22

Promised: 29 OCT 22

Date Sched:

Completed: 30 SEP 22

Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DWW	N/C

Parts

Part #	Description	Qty	Price	Total
2603892	GRAB HANDLE W/GRIP - BLACK - LEND A HAND	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPCI	LP - UNIT SALES	12.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Internal

LEND A HAND IS BENT.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: STAPLES NEED TO BE SET AND WOOD FILLER ADDED TO COMBINE NEXT TO ENTRY DOOR,

CORRECTION: set staples so they were flush and filled in with wood putty

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DWW	15.00

Subtotal for Job #2: 15.00

Job #3 - Warranty

COMPLAINT: THE WIRE LOOM IS HANGING UNDER THE REAR BUMPER



Customer #: 1000
BASDEN'S AMERICAN RV,



CORRECTION: I PUT THE WIRE BACK IN THE PLASTIC SLEVE AND PUT BLACK ELE. TAPE AROUND IT SC IT WOULDNT COME BACK OUT

Labor Code	Description	Mechanic	Total
Z99()	MISCELLANEOUS REPAIR	DWW	0.00
Z99()	MISCELLANEOUS REPAIR	DWW	30.00
Subtotal for Job #3:			30.00

Job #4 - Warranty

COMPLAINT: THE WATER HEATER DOOR IS OFF

CORRECTION: REINSTALLED WATER HEATER DOOR 2 SCREWS WERE MISSING I FOUND REPLACEMENT SCREWS FOR THE DOOR

Labor Code	Description	Mechanic	Total
Z99()	MISCELLANEOUS REPAIR	DWW	45.00
Subtotal for Job #4:			45.00

Job #5 - Warranty

COMPLAINT: THE WATER HEATER LATCH IS INOPERATIVE

CORRECTION: ADJUSTED SPRING AND LATCH

Labor Code	Description	Mechanic	Total
Z99()	MISCELLANEOUS REPAIR	DWW	0.00
Subtotal for Job #5:			0.00

Job #6 - Warranty

COMPLAINT: THE BACK SPLASH IS LOOSE BEHIND THE KITCHEN SINK

CORRECTION: GLUED BACKSPLASH BACK TO WALL

Labor Code	Description	Mechanic	Total
Z99()	MISCELLANEOUS REPAIR	DWW	45.00
Subtotal for Job #6:			45.00

Job #7 - Warranty

COMPLAINT: THE SHOWER SURROUND NEEDS TO BE SILICONED

CORRECTION: SILICONED THE SHOWER SURROUND

Labor Code	Description	Mechanic	Total
Z99()	MISCELLANEOUS REPAIR	DWW	60.00
Subtotal for Job #7:			60.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNIT'S WITH WASHING MACHINE OR ICEMAKER WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CORRECTION: winterized unit with denny and ben. used 3 gallons of antifreeze

Labor



Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DWW	N/C
Z990	WINTERIZE UNIT	DWW	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	3.00	N/C	N/C
10-7150	CONE WASHER SWIVEL SEAL	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Parts Total:	0.00
Labour Total:	195.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	195.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 05 Oct 2022

W/O: 62130
Promise Date: 29 OCT 22



Customer #: 1000
BASDENS AMERICAN RV,

