MYERS RV CENTER
SALES ★ PARTS ★ SERVICE

12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73874-1
Promised Date:
73874-1

WO #: 73874-1
Customer Name: 1000 - MYERS "RV" CENTER, INC.

Completed Date:
Invoice#:
Author: ADVISOR
Stock Desc: 9736 2027 LACROSSE 44PARK
Serial#: 012318
Chassis#: 5ZT2LC9B8VG012318
Miles/Hrs:
Tag#:
Purchased Date:
Warranty Date:

Date In: 09 SEP 26
Time In:

Job #02 - Warranty
COMPLAINT: LINO DAMAGED

CAUSE: Lino damaged due to the removable couch sections being pushed the wrong way causing it to not roll correctly and chew up the Lino flooring in multiple locations .

CORRECTION: Need to order flooring material in order to repair the 6 damaged tiles in the living room area . Will need to cut out the damaged tiles Individually along the seem of the tile squares very carefully making sure not to cut outside the false grout lines . Will need to repeat this step 6 times . Once all of the damaged tiles of the link are cut out and removed we will then need to go over the area where the old damaged tiles were and scrape away any and all left over adhesive left from the removed tiles . Once the bare floor is prepped and cleaned we can then cut out our new tiles from the new floor that we ordered insuring the tiles are the correct pattern .once new tiles are cut out we can start to re glue the new Lino squares in place insuring the edges are seamless and theres no bubbling etc .will need to use a combination of flooring adhesive and seam sealer in order to properly glue the new flooring tiles in place . Will need to repeat these steps 6 times for each tile that is damaged. requesting 1.3 for each square tile that needs to be replaced. for removal prep and install of new flooring tiles.

Labor

Job #	Description	Total
02	MISC LABOUR CODE (WARRANTY)	N/C

Subtotal for Job #02: **0.00**

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	**0.00**

Customer #: 1000
MYERS "RV" CENTER, INC.,
1000

© 2026 Integrated Dealer Systems

NOTICE:
DUE TO A LACK OF SPACE, A $15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____ Date: 09 Sep 2026

Customer Work Order

W/O: 73874-1
Promised Date: 08 SEP 26

73874-1

Customer #: 1000
MYERS "RV" CENTER, INC.,

1000

© 2026 Integrated Dealer Systems