

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b> 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	<b>CLAIM STATUS</b> Authorized <b>CLAIM</b> 1262060 <b>CLAIM ORIGIN</b> WEB <b>ORIGINAL CLAIM ID</b> <b>VIN</b> 5ZT2CARB0NU040281 <b>CHASSIS VIN</b> <b>MILEAGE</b> 0 <b>SITE/WAREHOUSE</b> 103 / 103 <b>ITEM #</b> CAT261BHS-8 <b>DEALER RO #</b> 68663 <b>CLAIM START DATE</b> 10/03/2022 <b>CLAIM END DATE</b> 01/01/1900	
<b>Labor rate:</b> \$150.00 <b>OWNER INFORMATION</b>		

Retail Date of Purchase

WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b> RC-003-22-00-004205	<b>Operational Description</b> 22V477, 2022-358 - BREAKAWAY SWITCH WIRING - INSPECT AND REWIRE - Recall/Electrical/Rewire/No Tread Code
----------------	--	--

**Complaint, Cause, Correction**

Original Note : bhoffman@americanrvcenter.com, 2022-10-03 16:23:54 :: JOB #22V477 BRAKE AWAY SWITCH WIRING RECALL REMOVED THE BATTERY DISCONNECT FROM THE FRAME, REMOVED THE BLACK WIRE FROM THE MINI BREAKER STUD. SNIPPED OFF THE EYELET STRIPPED BACK THE BLACK WIRE AND CRIMPED ON A 3/8 EYELET. CONNECTED THE BLACK WIRE FROM THE BREAKAWAT SWITCH TO THE STUD CONNECTED DIRECTLY TO THE BATTERY. REATTACHED THE BATTERY DISCONNECT TO THE FRONT CROSS MEMBER. TOOK PICTURES.

<b>Model #</b>	<b>Dlr Sub Hrs</b> 0.30	<b>Sub Labor Amt</b> \$45.00	
<b>Serial #</b>	<b>Appr Hrs</b> 0.30	<b>Appr Labor Amt</b> \$45.00	

Notes

<b>Submitted</b>	Labor Amt	\$45.00		<b>Approved</b>	Labor Amt	\$45.00
	Parts & Freight	\$0.00			Parts & Freight	\$0.00
	Total	\$45.00			Total	\$45.00

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_  
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_  
 All repairs described have been inspected and are satisfactory.