

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 68720
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 52535 - MARVIN BRISCOE
Address: 5355 IRONWOOD DR NEWBURGH, IN

47630

Phone: 618-316-4552

Stock Number: 11083 - 2022 SABRE 36BHQ 5ZT3SR1B0N6110433

VIN: 5ZT3SR1B0N6110433 HIN:

SER#: 5ZT3SR1B0N6110433

Mileage: 0

Work Order Comp: 15 OCT 22

Auth. No:

Dealer #:

Warr. Date: 30 APR 22

Work Order Date: 03 OCT 22

Inv #: 384000

WO # Job # Description JOB INFORMATION

68720 7 ZEBRA SHADE BEHIND COUCH HAS UNRAVLED
 ZEBRA SHADE SPRING HAS LOST TENSION IN BLIND BRACKET. BLIND WILL
 NOT RETRACT. I GAVE THE SIZE TO MATT FOR HIM TO ORDER A NEW ONE

68720 1 DINING ROOM SLIDE HAS SEPERATED FROM THE FLOOR
 REATTACHED LOWER SLIDE ROOM TRIM AND RESILICONED TRIM.WHEN I
 WALKED INTO THE UNIT THE TRIM WAS STICKING WAY OUT I NOTICED ONE
 OF THE TRIM SCREWS WAS MISSING. WHEN I WENT TO DO THE REPAIR I
 NOTICED THE MISSING SCREW WAS STUCK UNDER THE SLIDE ROOM. WHEN I
 MOVED THE SLIDE ROOM ALL THE WAY OUT I NOTICED THAT THE SCREW HAD
 DAMAGED THE FLOORING.

68720 2 LOOSE TRIM THAT IS BOWING AND NEEDS REATTACH
 REATTACHED TRIM WITH BRAD NAILS AND FILLED IN WITH WHITE WOOD
 PUTTY.

68720 3 WALL PANEL IN BUNKHOUSE TO THE RIGHT OF THE DOOR HAS SEPERATED
 AND CREATED A GAP
 NAILED PANNEL BACK UP WITH BRAD NAILS AND FILLED IN AREAS WITH
 WOOD PUTTY

68720 4 ACCENT LIGHTING ABOVE THE CROWN MOLDING ABOVE FRIDGE HAS FALLEN
 DOWN
 REATTACHED ACCENT LIGHTING ABOVE KITCHEN SLIDE ROOM

68720 5 SOME CAULKING IS MISSING IN THE SHOWER

Claim : 68720

 WO # Job # Description JOB INFORMATION

SILICONED SHOWER SURROUND

68720 PPERT #22-434 LIPPERT AWNING RECALL (INSPECTION)
 AWNING FABRIC IS OK. I TOOK PICS. FOR RECALL

68720 2V243 RECALL 22V243 LP QUICK CONNECT
 REPLACED LP QUICK CONNECT WITH A NEW VALVE AND USED PIPE THREAD
 SEALANT ON THREADS.

68720 8 TRIM OVER DINETTE IS BUCKLING
 NAILED TRIM BACK UP WITH BRAD NAILS AND FILLED IN AREAS WITH WOOD
 PUTTY.

 Part No Job# Description PARTS Qty Price Total

 F100140432 7 SHADE, 52" X 38" ZEBRA SHADE / 20 1.00 74.82 74.82

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.20 150.00 30.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.50 150.00 75.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.50 150.00 75.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.10 150.00 15.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.20 150.00 30.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.20 150.00 30.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.30 150.00 45.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 PERT MISC LABOUR CODE (EXTERNAL) 0.30 150.00 45.00
 Z990 V243 MISC LABOUR CODE (EXTERNAL) 0.10 150.00 15.00
 Z990 8 MISC LABOUR CODE (EXTERNAL) 0.10 150.00 15.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 7 UPS-SHADE 1.00 35.14 35.14

Parts Total: 74.82
 Labour Total: 375.00
 Sublet Total: 0.00
 Extras Total: 35.14

>>>> Claim Total: 484.96

Customer Signature: _____

Date: _____