

Pre-Authorization

Pre-Authorization number PA03278145			Reference no: 68731			Status: Approved		Approved by flins		Approved date 10/14/2022
Servicing Dealer	Name	Address		VIN		Retail sold on				
1194	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725		4YDTSGJ29P3100331						
Numbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction	
1	5101906B	Light, Clearance &	0.00	1.00	1.00		1	0.20	Complaint:THE REAR MARKER LIGHTS ON THE REAR ONE IS DIM AND THREE OTHERS DONT WORK Cause:THERE ARE 4 LIGHTS NEEDED REPLACED Correction:took out all 4 lights to check wiring and make sure they had power, they did, took off one light and tested with battery light was bad ,did same thing to other 3 and they were bad also, replaced all 4 lights and sealed, all is good. order 4 lights and give to parts dept. VCB	
2	5102024B	Light, Clearance &	0.00	0.10	0.10		1	0.10	Complaint:DRIVER SIDE FRONT MISSING ORANGE LENS Cause:MISSING ORANGE LENS Correction:CLOSE UP UNIT FROM SALES LOT AND BRING IN, FIND PARTS IN PARTS ROOM, AND BRING TO UNIT, GET LADDER AND INSTALL LENS	
3	3300206B	Blind - Venetian -	0.00	1.00	0.30		1	0.20	Complaint:REAR BLIND WILL NOT FOLD UP Cause:WILL NOT FOLD Correction:INSTALL NEW SHAD AND OLD VALANCE AT BACK WINDOW, PULL UNIT OUT AND SET UP ON SLES LOT, PUT OLD SHADE IN PARTS ROOM KRV – Labor time approved in accordance with Keystone RV's flat rate manual. VCB	
4	3102808B	Dinette Table - Re	0.00	1.00	0.20		1	0.20	Complaint:TABLE TOP IS BUSTED Cause:table top busted Correction:r&r table top KRV – Labor time approved in accordance with Keystone RV's flat rate manual.	
5	1210324B	Stabilizer Jack - H	0.00	0.10	0.10		1	0.10	Complaint:EMERGENCY CRANK HANDLE FOR REAR POWER STABILIZERS WAS MISSING @ CHECK-IN, NOTED. Cause:PART MISSING Correction:PART MISSING	

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company

Pre-Authorization

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
Pre-Authorization number PA03278145					1.70				

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company