

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 80425
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11782 - 2027 SPRINGDALE 1990BHS 4YDTSGH14VW100262

VIN: 4YDTSGH14VW100262 HIN: SER#: 4YDTSGH14VW100262

Mileage: 0 Work Order Comp: 21 OCT 26

Auth. No: Dealer #: 1194

Warr. Date: Work Order Date: 25 JUN 26 Inv #: 436114

WO # Job # Description JOB INFORMATION

80425 2 COUCH HAS SCUFF AND TEAR - POSSIBLY FROM THE FREEZER DOOR
FALLING DURING TRANSIT
On pdi found scuff of couch. Possibly caused by freezer door
falling off.
Took old kick plate off. Measured out all 5 screw spots from the
back. Started screw from the back to poke hole through the front
for a guide. Put new kick plate in. This time is over due to
having pulled this unit in 2 other times and had wrong part.

80425 3 BATTEN TRIM IN THE TOP BUNK AREA ON THE CEILING IS DAMAGED AND
NEEDS RELACED
On pdi found batten Strip in top bunk scratched and tore.
Replaced batten strip.

80425 1 DENT ON THE FLOOR FROM FREEZER DOOR FALLING OFF DURING TRANSPORT
On pdi found dent on floor caused by freezer door falling off
during transport.
INSTALLED FREEZER DOOR ` Ben is taking care of it.

Part No	Job#	Description	PARTS	Qty	Price	Total
772318	2	Sofa - Jackknife - Delfino - 60" -		0.00	726.70	0.00
778167	2	DECOR-DELFINO KICKBOARD 14.25 x 6		1.00	24.69	24.69
723869	3	Trim - Ceiling - 1.4" x 96" - 623		1.00	2.37	2.37

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	2	MISCELLANEOUS REPAIR		0.00	190.00	0.00

Claim : 80425

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990      2    MISCELLANEOUS REPAIR      0.20     190.00     38.00
Z990      3    MISCELLANEOUS REPAIR      0.20     190.00     38.00
Z990      1    MISCELLANEOUS REPAIR      0.20     190.00     38.00

```

```

*****
Job#  Sublet Description      SUBLET      Total
*****
1    REPAIR LINO                                425.00

```

```

*****
Excode  Job#  Description      EXTRAS      Qty      Price      Total
*****
FRT      2    UPS-KICK PANEL      1.00     53.27     53.27
FRT      3    UPS-CEILING TRIM    1.00     39.17     39.17

```

```

Parts Total:      27.06
Labour Total:     114.00
Sublet Total:     425.00
Extras Total:      92.44

```

>>>> Claim Total: 658.50

Customer Signature: _____

Date: _____