



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68738A
Promised Date: 29 OCT 22



Customer #:
27731



CUSTOMER WORK ORDER

WO #: 68738A
Customer: 27731 - MUNDY, BRIAN -
(812) 309-0306
Tag:
Author: BJW
Location: 0410 AA FIBER NEW
COMING OUT TO FIX CUSTOMER
NEEDS BACK 4-29

Stock #: 10953
Stock Desc: 2022 TT COACHMEN
SPIRIT XTR 2549BHX
Chassis #: 5ZT2SBPB8NS043677
Serial #: 5ZT2SBPB8NS043677
Mileage: 0
Licence:

Invoice #: 389580
Date In: 03 NOV 22
Promised: 29 OCT 22
Date Sched:
Completed: 10 APR 23
Warr. Date: 23 APR 22

Job #8 - Warranty

COMPLAINT: CHECK LINOLEUM FOR DENTS/HOLES. IN THE BATHROOM AND THE LIVING AREA.

CAUSE: BEN TO SUBLET WORK TO FIBERNEW.

Labor	Description	Mechanic	Total
Code			
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Sublet			Total
Description			
FIBER NEW			600.00
Subtotal for Job #8:			600.00

Job #1 - Internal

FIX OUTSIDE SPRAY PORT INSTALLED WRONG PER CUSTOMER IT WILL NOT CLOSE

Labor			Mechanic	Total
Code	Description		DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)			
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #1:				0.00

Job #2 - Internal

COMPLAINT: CUSTOMER CALLED BW ON 11/05/22. HE WAS WINTERIZING THE UNIT AT HOME AND NOTICED THAT THE SILVER END WAS BROKEN OFF OF THE COAX CABLE. CUSTOMER SAYS THAT WE REPLACED A SHELF UNDER THE TV AND THAT HIS COAX WAS NOT BROKEN PRIOR TO IT COMING TO US FOR REPAIRS. CUSTOMER WOULD LIKE TO HAVE COAX FIXED AT NO CHARGE TO HIM.

CORRECTION: CUT OFF COAX END AND INSTALLED NEW END AND SCREWED INTO TV.

Labor	Description	Mechanic	Total
Code			
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Subtotal for Job #2:			0.00

Job #3 - Internal

UNDER BELLY TAPE FELL OFF AND NEEDS TO BE TAPED UP





Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Subtotal for Job #3:			0.00

Job #4 - External

CRAIG TO INSTALL CUSTOMER WANTS ALL
 LOCKS CHANGED TO GLOBAL EXCEPT THE REAR
 CARGO DOOR

Other Services Code	Description	Qty	Price	Total
PARTS	4660 KEY-A-LIKE G375	5.00	N/C	N/C
Subtotal for Job #4:				0.00

Job #5 - Internal

COMPLAINT: CHECK AIR VENTS - CUSTOMER SAYS THEY
 CAN SEE STYROFOAM IN THE VENTS AND THEY
 AREN'T GETTING GOOD AIR FLOW

CORRECTION: TOOK COVERS OFF OF VENTS AND PUSHED DOWN TAPE FOR MORE FLOW,THE
 STYROFOAM THE CUSTOMER SEES,THATS WHAT THE CHANNELS ARE MADE FROM,TAPED OFF
 INSIDE AC UNIT,HAVE CUSTOMER SHUT VENT ON AC FOR MORE FLOW THROUGH CEILING.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Subtotal for Job #5:			0.00

Job #COVER-M - External

COMPLAINT: INSTALL MEDIUM SLIDE COVER 102" TO 132"

CORRECTION: UNBOXED COVER ,HAD TO SWITCH OUT SCREWS ON BRACKET,THEY WERE
 WRONG ONES ON BRACKET,INSTALLED BRACKETS ON SLIDES AND SECURES,INSTALLED
 AWNING RAIL ON COACH WITH PUTTY,SLIDE COVER INTO RAIL AND PUT ON ARMS AND
 SECURED,INSTALLED SCREWS IN AWNING AND ARMS,PULLED PINS ON AWNING AND
 TESTED,ALL GOOD.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Parts Part #	Description	Qty	Price	Total
00-0487	SOLERA TOPPER 97 Inch Fabric Length For Box Flange Width Range 92 Inch To 97-3/4 Inch	1.00	N/C	N/C
Subtotal for Job #COVER-M:				0.00

Parts Total: 0.00
 Labour Total: 0.00
 Sublet Total: 600.00
 Extras Total: 0.00
WORK ORDER TOTAL: 600.00



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 Apr 2023

W/O: 68738A
Promised Date:
29 OCT 22



Customer #:
27731

