



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68761
Promised Date: 29 OCT 22



Customer #: 43852
ABRAHAMSON, RODNEY



CUSTOMER WORK ORDER

WO #: 68761 (Appointment Date: 07 OCT 2022 - Time: 07:00am)

Customer: 43852 - ABRAHAMSON,
RODNEY - 618-439-1010

Tag:

Author: P.HUNT

Location: 1019 BH TO CLOSE WO

Stock #: 11017

Stock Desc: (11017) 2022 FOREST
RIVER CHEROKEE 294BH

Chassis #: 4X4TCKE23NX159873

Serial #: 4X4TCKE23NX159873

Mileage:

Licence:

Invoice #:

Date In: 07 OCT 22

Promised: 29 OCT 22

Date Sched:

Completed: 19 OCT 22

Warr. Date: 26 SEP 22

Job #1 - Warranty

COMPLAINT: INTERIOR DOORS NOT LATCHING BATHROOM AND PANTRY ONCE THE TRAILER IS
LEVELED AND JACKS DOWN

CORRECTION: TOOK OFF BOTH DOOR TRIM AND BOTH CATCHES AND SHIMED BOTH CATCHES
AND ADJUSTED BOTH CATCHES, AND PUT TRIM BACK ON, Hd camper level and slide out and all 4
jacks down.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	30.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 30.00

Job #2 - Warranty

COMPLAINT: OUTDOOR KITCHEN DOOR WILL ONLY LATCH WITH ONE LATCH, THE OTHERS ARE
NOT CATCHING

CORRECTION: adjusted door and all latches latch.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	30.00

Subtotal for Job #2: 30.00

Job #3 - Warranty

COMPLAINT: IN BEDROOM UNDER BED THERE IS A 2X2 BRACE THAT IS BROKEN

CORRECTION: had to pull out everything in basement door to get to slats underbed, had to take everything
off of bed to open up and had to take everything out under bed to pull out broken slats, measured new wood
and cut, installed new wood and put everything back under bed and put bed back together, put everything
back in outside door. see pictures.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	225.00

Subtotal for Job #3: 225.00





Customer #: 43852
 ABRAHAMSON, RODNEY



Job #4 - Warranty

COMPLAINT: DOOR CLIP ON OUTSIDE HATCH IS BROKE ON DOORSIDE

CORRECTION: took off catch and had one ordered.installed new latch.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	15.00

Parts

Part #	Description	Qty	Price	Total
20-1436	Access Door Latch; Use To Keep RV Baggage Doors Closed; Square; Black	1.00	5.26	5.26

Subtotal for Job #4: 20.26

Job #5 - Warranty

COMPLAINT: ENTRY DOOR IS STICKING, NEEDS ADJUSTED

CORRECTION: door was hitting screw head,changed out screw with flat head screw,dosent hit.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	45.00

Subtotal for Job #5: 45.00

Job #6 - Internal

COMPLAINT: INSTALL A SCREEN DEFENDER AND SCREEN SHOT ON UNIT

CORRECTION: GOT PARTS FROM CRAIG ON FRIDAY,FIGURED OUT HOW TO PUT SCREEN DEFENDER ON SCREEN DOOR,STOPED ON FRIDAY AND FINISHED ON MONDAY,CUSTOMER BROUGHT IN SCREEN SHOT AND IT WAS WRONG GOT WITH CRAIG TO GET RIGHT ONE BECAUSE WRONG PARTS IN BOXES,INSTALLED SCREEN SHOT AND SCREEN DEFENDER.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #6: 0.00

Job #LIPPERT - Warranty

COMPLAINT: #22-434 LIPPERT AWNING RECALL (INSPECTION)

CORRECTION: UNIT WAS IN RECALL ALL LOOKED GOOD

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	45.00

Subtotal for Job #LIPPERT: 45.00

Parts Total: 5.26
 Labour Total: 390.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 395.26

