



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68816
Promised Date: 30 SEP 22

CUSTOMER WORK ORDER

WO #: 68816

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: 1025 CHECK PREAUTH

Stock #: 11245

Stock Desc: 2023 TT RIVERSIDE RV
INTREPID 210

Chassis #: 59CCC2326PL006535

Serial #: 59CCC2326PL006535

Mileage: 0

Licence:

Invoice #:

Date In: 12 OCT 22

Promised: 30 SEP 22

Date Sched:

Completed: 20 OCT 22

Warr. Date:

Job #1 - Warranty

COMPLAINT: THE INSIDE DOOR TRIM IS FALLING OFF.

CAUSE: THE INSIDE DOOR TRIM IS FALLING OFF.

CORRECTION: Reattached trim along side of entrance door. Filled all nail holes with matching putty.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	15.00

Subtotal for Job #1: 15.00

Job #2 - Internal

COMPLAINT: THE CIRCUIT BREAKER ON THE FRONT TONGUE BROKEN

CAUSE: THE CIRCUIT BREAKERS ON THE FRONT TONGUE ARE BROKEN.

CORRECTION: Removed battery box for access to circuit breakeer mounting. Removed all wires from broken circuit breakers. Mounted new circuit breakers that are metal instead of plastic. Reconnected all wiring to circuit breakers. Shortened both battery cables that were "TOO" long to fit application. Installed new battery cable ends. Remounted battery box.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
19-1441	16-3030 30A CIRCUIT BREAKER	1.00	N/C	N/C
55-8174	CIRCUIT BREAKER-50A	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Parts Total:	0.00
Labour Total:	15.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	15.00



Customer #: 1000
BASDEN'S AMERICAN RV,