

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 68825
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 20963 - HAROLD E. HANCOCK
Address: 6344 ST RT 370 E PO BOX 155
SEBREE, KY
42455
Phone: 270-318-0560
Stock Number: 10965 - 2022 COUGAR HALF-TON 32BHS 4YDFCGR29N2504733
VIN: 4YDFCGR29N2504733 HIN: SER#: 4YDFCGR29N2504733
Mileage: 0 Work Order Comp: 28 OCT 22
Auth. No: Dealer #: 1194
Warr. Date: 18 OCT 22 Work Order Date: 13 OCT 22 Inv #: 384619

WO # Job # Description JOB INFORMATION

68825 3 THE SHOWER SURROUND IS LOOSE ON THE EDGE
THE SHOWER SURROUND IS LOOSE ON THE EDGE.
Shower surround is loose and bowed on edge. Added plastic push
rivets to edge inbowed area. Resealed edge of shower surround
with clear silicone.

68825 1 BATHROOM DOOR WILL NOT LATCH CLOSED
BATHROOM DOOR WILL NOT LATCH CLOSED.
Latch place mounted too low. Removed latch plate. cutout hole
in door frame to raise latch plat. Remounted latch plate in new
holes. Checked operation of door. Door now closes and latches
closed.

68825 2 TRIM IN BUNK ROOM LOOSE
TRIM IN BUNK ROOM LOOSE.
Door frame trim and wall panel loose on hinge side of door. Trim
too long and bowed out. Removed door frame trim and cut off at
bottom ti fit. Secured wall panel on edge to wall stud.
Remounted door frame trim and filled all nail holes with putty.

Part No Job# Description PARTS Qty Price Total

20-0735 3 25pk 1"PLASTIC RIVET WHIT 1.00 6.89 6.89

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 3 MISCELLANEOUS REPAIR 0.20 150.00 30.00

Claim : 68825

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	1	MISCELLANEOUS REPAIR	0.20	150.00	30.00
Z990	1	MISCELLANEOUS REPAIR	0.00	150.00	0.00
Z990	2	MISCELLANEOUS REPAIR	0.20	150.00	30.00

Parts Total:	6.89
Labour Total:	90.00
Sublet Total:	0.00
Extras Total:	0.00

>>>> Claim Total: 96.89

Customer Signature: _____

Date: _____