

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 68830
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 51966 - NEONA F. UNDERHILL
Address: 5333 LEE ACRES RD
BOONVILLE, IN
47601
Phone: (812) 641-6070
Stock Number: 2022 SPRINGDALE 202RD 4YDTSGJ23N3100452
VIN: 4YDTSGJ23N3100452 HIN: SER#: 4YDTSGJ23N3100452
Mileage: Work Order Comp: 15 OCT 22
Auth. No: Dealer #: 1194
Warr. Date: 23 OCT 21 Work Order Date: 14 OCT 22 Inv #: 383995

WO # Job # Description JOB INFORMATION

68830 2 CUSTOMER NOTICED THAT WATER WAS IN THE FLOOR OF THE BATHROOM. HE
FOUND THAT THE TOILET BOWL WAS FULL OF WATER. WHEN HE NOTICED
THIS, THE FRESH TANK SHOWED EMPTY. HE STEPPED ON THE FLUSH PEDAL
AND MORE WATER CAME OUT. CUSTOMER DOESN'T THINK THAT THE PUMP WAS
ON AT THE TIME, BUT HE'S NOT SURE.

CONNECT AIR LINE TO CITY WATER INLET AND FOUND WATER RUNNING IN
TOILET, CHECK AND FOUND WATER VALVE LEAKING DOMETIC 310 S#
11983746, GET NEW VALVE AND INSTALL, WATER TEST FOR LEAKS

68830 3 THE KNIFE VALVE ON THE GREY TANK WILL NOT CLOSE
I FOUND THAT THE GATE VALVE HAD GLUE IN IT. I TRIED TO CLEAN OUT
THE VALVE. I COULD NOT REMOVE THE GLUE. I HAD TO REPLACE THE
VALVE. TESTED THE VALVE AFTER INSTALL AND IT IS WORKING AS IT
SHOULD.

Part No Job# Description PARTS Qty Price Total

385311641 2 310 WATER VALVE - SEALAND 1.00 45.51 45.51
89-8476 3 1 1/2" WASTE VALVE 1.00 12.13 12.13

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 2 MISC LABOUR CODE (EXTERNAL) 0.75 150.00 112.50
Z990 3 MISCELLANEOUS REPAIR 0.50 150.00 75.00

Claim : 68830

 Lab Code Job# Description LABOUR Hrs Rate Total

Parts Total: 57.64
 Labour Total: 187.50
 Sublet Total: 0.00
 Extras Total: 0.00
 >>>> Claim Total: 245.14

Customer Signature: _____

Date: _____