



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68989
Promised Date:
19 OCT 22

CUSTOMER WORK ORDER

WO #: 68989 (Appointment Date: 19 OCT 2022 - Time: 07:00am)

Customer: 5098 - PUTLER, OTTIS D. -
812-449-8281

Tag: UNIT NOT HERE

Author: BH

Location: 1116 FIND OUT FROM PH IF
CUSTOMER HAS BROUGHT UNIT
BACK YET

Stock #: 10833

Stock Desc: (10833) 2022 FOREST
RIVER CHEROKEE GREY WOLF
23MK

Chassis #: 4X4TCKY28NK082426

Serial #: 4X4TCKY28NK082426

Mileage:

Licence:

Invoice #:

Date In: 19 OCT 22

Promised: 29 OCT 22

Date Sched:

Completed: 16 NOV 22

Warr. Date: 03 JUN 22

Job #1 - Warranty

COMPLAINT: ENTRY DOOR DONT LOCK RIGHT, STRIKER PLATE IS REMOVED AND LAYING ON THE COUCH

CORRECTION: PUT STRIKER PLATE BACK ON AND ADJUSTED.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	15.00
Subtotal for Job #1:			15.00

Job #2 - Warranty

COMPLAINT: SLIDE ROOM MOTORS SEEM LIKE THEY ARE WORKING HARDER THAN THEY SHOULD. SKIPS ALONG SOMETIMES AS IT COMES IN

CORRECTION: TESTED MOTOR AND CABLE AND THEY ARE GOOD, DID OVERRIDE ON BOX AND IT WILL STILL NOT COME OUT SOMETHING IN RAIL IS HOLDING IT UP, WONT KNOW WHAT UNTIL I TAKE APART. PULLED ENTIRE SYSTEM APART AND INSTALLED NEW HAD TO DRILL NEW HOLES AND MEASURE SYSTEM BECAUSE IT WAS THE OLDER SYSTEM AND THE SYSTEM ON THE TRAILER WAS INVERTED. I THEN SEALED AND REMOUNTED THE CONTROL BOARD UNDER THE ROOM.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	150.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	600.00

Parts

Part #	Description	Qty	Price	Total
6544	SLIDEROOM SYSTEM (RACK)	1.00	823.65	823.65
Subtotal for Job #2:				1,573.65

Job #3 - Warranty

COMPLAINT: THE BRAKET THAT HOLD THE BED UP ARE BROKEN

CORRECTION: TOOK OFF HINGE BECAUSE IT IS BROKEN, INSTALLED SHOCKS BACK IN PLACE, CRAIG IS GETTING PARTS. OTHER HINGE WAS BENT ALSO, I INSTALLED 3 HINGES FOR MORE SUPPORT, REINSTALLED SHOCKS.



Customer #:
5098





Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	30.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Other Services				
Code	Description	Qty	Price	Total
PARTS	803720 ORB 3" SURFACE HINGE	2.00	5.22	10.44
Subtotal for Job #3:				40.44

Job #4 - Warranty

COMPLAINT: WOOD PANEL BELOW COUNTER NEAR FRIDGE/STOVE HAS COME LOOSE

CORRECTION: HAD TO TAKE OFF FURNANCE COVER AND TAKE OUT CONVERTER TO GET TO BACK SIDE OF PANEL TO REATTACH,ALSO FOUND VENT TUBE WAS OFF OF FURNANCE REATTACHED TUBE TO FURNANCE AND PANEL AND PUT CONVERTER BACK IN.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	15.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00
Subtotal for Job #4:				15.00

Job #5 - Warranty

COMPLAINT: STOVE COVER HINGE HAS POPPED LOOSE

CORRECTION: TOOK COVER OFF BECAUSE IT WAS INSTALLED WRONG FROM FACTORY,INSTALLED HINGES BACK IN PLACE WHERE IT WAS SUPPOSE TO BE AND REINSTALLED TOP.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	15.00

Subtotal for Job #5: 15.00

Job #22V243 - Warranty

COMPLAINT: RECALL 22V243 LP QUICK CONNECT

CORRECTION: TOOK OFF OLD QUICK CONNECT AND REPLACED WITH NEW AND TESTED ,NO LEAKS.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	45.00

Subtotal for Job #22V243: 45.00

Parts Total: 823.65
 Labour Total: 870.00
 Sublet Total: 0.00
 Extras Total: 10.44
WORK ORDER TOTAL: 1,704.09

