

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	CLAIM STATUS Authorized CLAIM 1290011 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CARB3NU039464 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 103 / 103 ITEM # CAT263BHCKLE DEALER RO # 69027 CLAIM START DATE 10/24/2022 CLAIM END DATE 01/01/1900	
Labor rate: \$150.00 OWNER INFORMATION JUSTIN L BULLARD 5 VICTORY LN Fairfield, IL 62837 USA		
Retail Date of Purchase 02/12/2022	WARRANTY EXPIRATION DATE 02/12/2023	

Claim Line Details

Labor

Line# 1	Operation Code RC-026-01-00-004186	Operational Description 22V243, 2022-181 - FLEXTech QUICK DISCONNECTS - REMEDY (INCLUDES INSPECTION) - Recall/LP Gas System/Replace/No Tread Code Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-10-24 12:04:40 :: RECALL 22V243 LP QUICK CONNECT 22V243 - RECALL 22V243 LP QUICK CONNECT. Moved unit into shop from service lot. Checked Quick Connect for Recall part. Quick connect is affected recall part. Removed quick connect part. Cleaned threads per recall instructions. Applied thread seal and installed new part. Performed 3 min. drop test. No leaks.								
	Model # Serial #	<table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Dlr Sub Hrs</td> <td style="width: 10%;">0.30</td> <td style="width: 30%;">Sub Labor Amt</td> <td style="width: 30%;">\$45.00</td> </tr> <tr> <td>Appr Hrs</td> <td>0.30</td> <td>Appr Labor Amt</td> <td>\$45.00</td> </tr> </table>	Dlr Sub Hrs	0.30	Sub Labor Amt	\$45.00	Appr Hrs	0.30	Appr Labor Amt	\$45.00
Dlr Sub Hrs	0.30	Sub Labor Amt	\$45.00							
Appr Hrs	0.30	Appr Labor Amt	\$45.00							

Notes

Labor

Line# 2	Operation Code RC-003-22-00-004205	Operational Description 22V477, 2022-358 - BREAKAWAY SWITCH WIRING - INSPECT AND REWIRE - Recall/Electrical/Rewire/No Tread Code Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-10-24 12:07:34 :: JOB #22V477 BRAKE AWAY SWITCH WIRING RECALL BRAKE - JOB #22V477 BRAKE AWAY SWITCH WIRING RECALL. Removed all tape around factory cut hole in underbelly. Removed brake-away switch from frame mounting. Took picture of back of switch and brake-away wire going to small breaker. Cut wire off at terminal. Rerouted wire to battery side of disconnect switch. Installed new ring terminal. Removed nut on disconnect switch and installed wire from brake-away switch. Reinstalled nut on back of switch and tightened. Remounted brake-away switch on frame. Sealed up hole in underbelly with underbelly tape.								
	Model # Serial #	<table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Dlr Sub Hrs</td> <td style="width: 10%;">0.30</td> <td style="width: 30%;">Sub Labor Amt</td> <td style="width: 30%;">\$45.00</td> </tr> <tr> <td>Appr Hrs</td> <td>0.30</td> <td>Appr Labor Amt</td> <td>\$45.00</td> </tr> </table>	Dlr Sub Hrs	0.30	Sub Labor Amt	\$45.00	Appr Hrs	0.30	Appr Labor Amt	\$45.00
Dlr Sub Hrs	0.30	Sub Labor Amt	\$45.00							
Appr Hrs	0.30	Appr Labor Amt	\$45.00							

Notes

Labor

Line# 3	Operation Code 10-11-01-00-000205	Operational Description Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Replace/No Tread Code Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-10-24 12:09:01 :: CHECK GAPS ON EACH LOWER
----------------	---	--

CORNER OF THE SLIDE ROOM WHEN IT IS IN OR OUT. HE BELIEVES THAT A PART OF THE SEAL MIGHT HAVE COME OFF. CHECK GAPS ON EACH LOWER CORNER OF SLIDE ROOM WHEN IT IS IN OR OUT. CUSTOMER BELIEVES THAT A PART OF THE SEALMIGHT HAVE COME OFF. Checked lower flap seals. Seals are being pulled in under slide room when running room in and tearing flap seals. 10/24/2022: Turned in parts request for nw flap seals.

Model #
Serial #

Dlr Sub Hrs 2.50
Appr Hrs 2.00

Sub Labor Amt \$375.00
Appr Labor Amt \$300.00

Notes

EXCESSIVE AMOUNT REQUESTED. ADJUSTED TO TYPICAL TIME FOR REPAIR BASED UPON JOB DESCRIPTION AND PHOTOS.

Submitted

Labor Amt \$465.00
Parts & Freight \$0.00
Total \$465.00

Approved

Labor Amt \$390.00
Parts & Freight \$0.00
Total \$390.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.