

e-Authorization

11/3/20
09:55:54

3-Authorization number PA03295695 Reference no: 69057 Status: Approved Approved by papca
 Billing Name Address Address VIN Retail sold on Approved date 11/3/2022

34 Basden's American RV Basden's American RV 4YDFCGS2XP2501577 10/27/2022
 600 E Baseline Rd
 Evansville, IN 47725

| Job operation | Description | Sublet | Sub hours | Approved hours | Actual hours | Qty | Base hours | Complaint / Cause / Correction |
|---------------|-------------------|--------|-----------|----------------|--------------|-----|------------|---|
| 1 4154014B | Water Heater - Ta | 0.00 | 1.00 | 0.50 | | 1 | 1.00 | Complaint:WATER HEATER EXHAUST PIPE NOT COMING OUT THE HOLE WATER HEATER INSTALL WRONG Cause:INSTALL WRONG Correction:REMOVE WATER HEATER DOOR, REMOVE MOUNTING SCREWS FOR WATER HEATER REPOSITION WATER HEATER, REMOUNT WATER HEATER INSTALL DOOR, COP SEAL DOOR FRAME KRV- approve to realign (do not replace water heater) |
| 2 6109206B | Sewer Cap | 0.00 | 0.30 | 0.30 | | 1 | 0.10 | Complaint:DOORS FOR SEWER HOSE CARRIER HAVE BROKEN HINGES. Cause:FOUND DOORS BROKEN NEED TO REPLACE Correction:REPLACE BOTH DOOR KRV - Labor time adjusted allowing for proper repair procedure to be performed. |

3-Authorization number PA03295695 0.80

1 paper claims ~~only~~ use one pre-authorization number per warranty claim for
 2 please a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the