



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69066

CUSTOMER WORK ORDER

WO #: 69066

Customer: 1000 - BASDEN'S AMERICAN

RV -

Tag:

Author: BH

Location: 1031 CHCEKDCK PREAUTH

Stock #: 11174

Stock Desc: 2023 TT COACHMEN

FREEDOM EXPRESS 294BHDS

Chassis #: 5ZT2FEUB7PW026729

Serial #: 5ZT2FEUB7PW026729

Mileage: 0

Licence:

Invoice #:

Date In: 25 OCT 22

Promised:

Date Sched:

Completed: 28 OCT 22

Warr. Date:

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: WINTERIZE LOT UNIT

CORRECTION: WINTERIZED LOT UNIT

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	RAB	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDI NEW TRAVEL TRAILER

CORRECTION: PDIED NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C



Customer #: 1000
BASDEN'S AMERICAN RV,



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Internal

COMPLAINT: SHOWER SURROUND NEEDS SEALED

CAUSE: SHOWER SURROUND NOT SEALED COMPLETELY NEEDS SEALED UP

CORRECTION: SEALED UP SHOWER SURROUND

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
500627	CLEAR SIKASIL PLUS	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: THE KITCHEN SINK IS LEAKING NEAR THE DRAIN

CAUSE: the kitchen sink was leaking near the lower elbow connector. the connection was not screwed on tight at all causing a leak

CORRECTION: the kitchen sink was leaking near the lower elbow connector. the connection was not screwed on tight at all causing a leak. tightened connector and tested

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	30.00

Subtotal for Job #2: 30.00

Parts Total: 0.00
Labour Total: 30.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 30.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 28 Oct 2022

Customer #: 1000
BASDEN'S AMERICAN RV,

