



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69071
Promised Date: 29 OCT 22

CUSTOMER WORK ORDER

WO #: 69071 (Appointment Date: 28 OCT 2022 - Time: 10:00am)

Customer: 36836 - STOCKTON,
RAYMOND A. - 618-384-7714

Tag:

Author: BH

Location: 1031 CHECK PREAUTH

Stock #: 11057

Stock Desc: 2022 TT RIVERSIDE RV

INTREPID 240DDS

Chassis #: 59CCC3625NL004595

Serial #: 59CCC3625NL004595

Mileage:

Licence:

Invoice #: 384503

Date In: 25 OCT 22

Promised: 29 OCT 22

Date Sched:

Completed: 27 OCT 22

Warr. Date: 21 APR 22

Job #WINTER - External

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CORRECTION: WINTERIZED AND DID EVERYTHING ON SHEET.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DGH	N/C
Z990	WINTERIZE UNIT	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #2 - External

COMPLAINT: BLACK TANK ALWAYS SHOWS 2/3 FULL

CORRECTION: hooked hose to black tank flush and vacuum breaker was leaking it had stink bugs in it so i replaced it and turned water back on and flushed tank, got down to 1/3 and had to use hose and went in through toilet and cleaned out tank, had lots of toilet paper build up on bottom of tank, customer needs to use more water, reads empty now.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
282770	94239 VACUUM BREAKER/CHECK VALVE	1.00	N/C	N/C

Subtotal for Job #2: 0.00



Customer #: 36836
STOCKTON, RAYMOND A.



Customer #: 36836
 STOCKTON, RAYMOND A.



Job #3 - Warranty

COMPLAINT: BED WOOD ASSIST SHOCK BROKE OFF TO LIFT THE BED

CORRECTION: pulled out staples and moved bracket to be straight and stapled wood back in place and reattached shock.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	45.00

Subtotal for Job #3: 45.00

Job #4 - Internal

COMPLAINT: AWNING FABRIC SAGS ON THE ENTRY DOOR

CORRECTION: extended awning out and found when customer changed shock the washers were missing in arm, went down to shop and got awning arm and got washers to fix, put washers in and tightened and it works fine now.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: A/C HAS POOR PERFORMANCE

CORRECTION: took plenum down to hook test box to ac control board and ac comes on and compressor comes on it works fine, but when it is hooked uP STOCK COMPRESSOR WONT COME ON, FOUND 4 WIRE NUTS FELL OFF TO WIRES, REDID WIRE NUTS AND COMPRESSOR COMES ON NOW AND GOES OFF TURNED HEAT ON AND GOT WARM IN CAMPER AND TURNED ON AC AND IT WORKS, IT IS REALLY TO COLD TO TEST, NEED WARMER WEATHER TO GET TRUE TEST.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	75.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Subtotal for Job #5: 75.00

Job #6 - Warranty

COMPLAINT: DOOR SHOCK IS PULLING OUT CHECK AND ADVISE

CORRECTION: TIGHTENED UP BALL SOCKET.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	15.00

Subtotal for Job #6: 15.00

Parts Total: 0.00
 Labour Total: 135.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 135.00

