

# e-Authorization

11/7/20  
10:50:39

3-Authorization number PA03297183 Reference no: 69105 Status: Approved Approved by anglr Approved date 11/4/2022  
 Billing Name Address Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDFCGN29N2501028 10/23/2021  
 600 E Baseline Rd  
 Evansville, IN 47725

Item	Root operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3201816A	Decorative Wood	0.00	0.20	0.20		1	0.10	Complaint: TRIM INSIDE COMING OFF Cause: TRIM IS TOO LONG AND HAS PUSHED ITSELF OUT. Correction: REMOVED TRIM. REMOVED BRAD NAILS. CUT 1/4 INCH OFF THE BOTTOM ON RADIAL SAW. SECURED TRIM WITH BRAD NAILS. FILLED HOLES WITH PUTTY.
2	5102406B	Light, 12V Interior	0.00	0.30	0.20		1	0.20	Complaint: MOTION LIGHT STAYING ON ALL THE TIME Cause: light needs replaced Correction: pulled unit into shop. removed light cover. removed mounting screws. cut wires. crimped wires on new light, secured light. installed cover. parked unit in done row.
3	4116414A	Furnace - Atwood	0.00	1.00	0.50		1	0.30	Complaint: FURNANCE NOT WORKING. RUNS FOR A SHORT TIME THEN KICKS OFF AND SAYS THAT A FUSE IS BLOWN Cause: pulled unit into shop. hooked up to power and turned on gas. furnace ran for 10 minutes and then stopped. turned off gas. removed duct work and exhaust, removed mounting screws. pulled furnace. ran furnace on bench tester for an hour with no issues. re installing furnace to see if anything changes Correction: Grabed a normal 15 amp fuse and installed. Turned on furnace and ran for 15 minutes with no issues. Cleaned up mess and parked unit

Qty	Hours	Sub operation	Description
1	0.10	4119806B	Furnace - Atwood/Dometic Hydrofla

KRV - Labor time adjusted allowing for proper repair procedure to be performed.

KRV - Labor time approved in accordance with Keystone RV's flat rate manual.  
 VCB: Vendor Charge Back item. (This is a Keystone RV Internal notation only)

paper claims only use one pre-authorization number per warranty claim for

multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

# e-Authorization

11/7/20  
10:50:39

Job Root or operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
3-Authorization number PA03297183				0.90				

For paper claims only use one pre-authorization number per warranty claim for  
multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim  
form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the