



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 69105

### CUSTOMER WORK ORDER

WO #: 69105 (Appointment Date: 27 OCT 2022 - Time: 02:00pm)

Customer: 28029 - ROSS, WILLIAM -  
270-860-6702

Tag:

Author: D.HINTON

Location: 1110 CHECK PREAUTH

Stock #: 10964

Stock Desc: (10964) 2022 KEYSTONE  
COUGAR HALF-TON 29RKS

Chassis #: 4YDFCGN29N2501028

Serial #: 4YDFCGN29N2501028

Mileage:

Licence:

Invoice #: 385007

Date In: 27 OCT 22

Promised:

Date Sched:

Completed: 31 OCT 22

Warr. Date: 28 OCT 21

#### Job #1 - Warranty

COMPLAINT: TRIM INSIDE COMING OFF

CAUSE: TRIM IS TOO LONG AND HAS PUSHED ITSELF OUT.

CORRECTION: REMOVED TRIM. REMOVED BRAD NAILS. CUT 1/4 INCH OFF THE BOTTOM ON  
RADIAL SAW. SECURED TRIM WITH BRAD NAILS. FILLED HOLES WITH PUTTY.

#### Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	30.00

**Subtotal for Job #1: 30.00**

#### Job #2 - Warranty

COMPLAINT: MOTION LIGHT STAYING ON ALL THE TIME

CAUSE: light needs replaced.

CORRECTION: pulled unit into shop. removed light cover. removed mounting screws. cut wires. crimped  
wires on new light, secured light. installed cover. parked unit in done row.

#### Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	30.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00

#### Parts

Part #	Description	Qty	Price	Total
592487	Light - LED - Motion Sensor - Courtesy	1.00	7.62	7.62
	Light - 12V - Black			

#### Other Services

Code	Description	Qty	Price	Total
FRT	UPS-LIGHT	1.00	15.21	15.21

**Subtotal for Job #2: 52.83**

#### Job #3 - Warranty

COMPLAINT: FURNANCE NOT WORKING. RUNS FOR A SHORT TIME THEN KICKS OFF AND SAYS  
THAT A FUSE IS BLOWN

CAUSE: pulled unit into shop. hooked up to power and turned on gas. furnace ran for 10 minutes and then  
stopped. turned off gas, removed duct work ands exhaust, removed mouting screws. pulled furnace. ran  
furnace on bench tester for an hour with no issues. re installing furnace to see if anything changes. Installed



Customer #: 28029  
ROSS, WILLIAM



furnace into cubbyhole. Hooked up power and thermostat wires. Hooked up gas line. Hooked up all duct work. Secured furnace to floor. Turned on gas and turned on furnace. Furnace ran for about a minute and stopped. I looked over to the breaker panel and noticed that the fuse light was lit up red. Factory had installed a breaker that resets automatically. These Breakers often cause a lot of problems on most appliances that they are installed in.

CORRECTION: Grabed a normal 15 amp fuse and installed. Turned on furnace and ran for 15 minutes with no issues. Cleaned up mess and parked unit

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	75.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.50	0.50

**Subtotal for Job #3: 75.50**

**Job #4 - Internal**

COMPLAINT: THE ENTERTAINMET SLIDE WALL FLEXES WHEN IT GOES OUT.

CAUSE: RAN SLIDE ROOM IN AND OUT SEVERAL TIMES. DIDNT SEE ANY FLEXING OR MOVEMENT THAT ISN'T NORMAL. SLIDE ROOM WILL MOVE SLIGHTLY OVER "GUIDE PLATE" UNDERNEATH.

CORRECTION: NO CORRECTIONS AT THIS TIME.

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C

**Subtotal for Job #4: 0.00**

**Job #LP - External**

COMPLAINT: FILL LP DRIVERS SIDE TANK

CAUSE: FILL LP TANK

CORRECTION: FILLED TANK TO FULL. 6 GALLONS

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

**Other Services**

Code	Description	Qty	Price	Total
LPG	LP GAS	6.00	N/C	N/C

**Subtotal for Job #LP: 0.00**

Parts Total: 7.62  
 Labour Total: 135.00  
 Sublet Total: 0.00  
 Extras Total: 15.71  
**WORK ORDER TOTAL: 158.33**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.



Customer #: 28029  
ROSS, WILLIAM

