



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69115
Promised Date: 31 OCT 22

CUSTOMER WORK ORDER

WO #: 69115 (Appointment Date: 28 OCT 2022 - Time: 10:30am)

Customer: 52399 - TOELLE, SCOTT -
812-483-1767

Tag:

Author: BH

Location: 1110 CHECK PARTS

Stock #: 11140

Stock Desc: 2022 5W KEYSTONE

COUGAR 316RLS

Chassis #: 4YDFCGR24N2509449

Serial #: 4YDFCGR24N2509449

Mileage: 0

Licence:

Invoice #: 384944

Date In: 28 OCT 22

Promised: 31 OCT 22

Date Sched:

Completed: 31 OCT 22

Warr. Date: 17 JUN 22

Job #WINTER - External

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: WINTERIZED CUSTOMER UNIT

CORRECTION: WINTERIZED CUSTOMER UNIT TOOK 2 GALS

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #LIPPERT - Warranty

Transferred to BAS*69122 on 28 OCT 22

Estimate amount was 0.00

#22-434 LIPPERT AWNING RECALL (INSPECTION)

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Subtotal for Job #LIPPERT: 0.00

Job #3 - Internal

COMPLAINT: WATER HEATER DOOR FLEW OFF WHEN TRAVELING

CAUSE: WATER DOOR HEATER FLEW OFF DURING TRAVEL

CORRECTION: INSTALLED NEW WATER HEATER DOOR

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------

Printed On: 11/4/2022 11:26:54AM

© 2022 Integrated Dealer Systems



Customer #: 52399
TOELLE, SCOTT



Z990	MISC LABOUR CODE (EXTERNAL)		RAB	N/C
Parts				
Part #	Description	Qty	Price	Total
09-0038	6255AEB BLK FLUSH 6 GAL WH DOOR	1.00	N/C	N/C
Subtotal for Job #3:				0.00

Job #4 - Warranty

COMPLAINT: BATHROOM VENT FAN LID NOT CLOSING ALL THE WAY

CAUSE: VENT LID NOT CLOSING ALL THE WAY DUE TO SLIPING ON GEAR OF VENTLINE OPERTOT MECHANSIM NEEDS NEW ONE

CORRECTION: BRING IN FROM LOT, NEED ADAPTER ON 5W, HAVE TO FIND WAS LEFT ON UNIT OUT ON LOT, GET PARTS, IS FULL VENT, BH SEAD TO INSTALL FULL VENT, PEAL OFF SEALER FROM VENT, REMOVE SCREWS, PULL VENT UP, INSTALL NEW VENT WITH PUTTY TAPE, NEW SCREWS, AND DICOR, CLEAN UP INSIDE SAWDUST FROM VENT THAT FELL OUT REMOVING VENT

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISCELLANEOUS REPAIR	JP	0.00
Z990	MISCELLANEOUS REPAIR	JP	75.00
Z990	MISCELLANEOUS REPAIR	JP	0.00
Z990	MISCELLANEOUS REPAIR	JP	0.00
Z990	MISCELLANEOUS REPAIR	JP	0.00

Parts				
Part #	Description	Qty	Price	Total
646216	VENT - ROOF - 12V - NEW LOCK	1.00	36.51	36.51
PUTTY	PUTTY TAPE - ROLL	1.00	7.12	7.12
13-1320	PW HAPS FREE SELF-LEVELING DICOR	2.00	6.20	12.40

Other Services				
Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	24.74	24.74
Subtotal for Job #4:				155.77

Job #5 - Warranty

COMPLAINT: DRIVER SIDE SLIDE LOWER J WRAP IF FLAPPING WHEN DRIVING

CAUSE: J WRAP ON DRIVER SIDE WAS NOT SCREWED TIGHT TO THE BRACKETS CAUSING IT TO FLPA

CORRECTION: TIGHTED UP SCREWS

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	30.00
Subtotal for Job #5:			30.00



W/O: 69115
Promised Date: 31 OCT 22

Parts Total:	56.03
Labour Total:	105.00
Sublet Total:	0.00
Extras Total:	24.74
WORK ORDER TOTAL:	185.77

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 04 Nov 2022



Customer #: 52399
TOELLE, SCOTT

