



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69215
Promised Date:
24 DEC 22

CUSTOMER WORK ORDER

WO #: 69215

Customer: 1000 - BASDEN'S
AMERICAN RV -

Tag:

Author: PH

Location: 1205 CHECK PREAUTH

Stock #: 10845

Stock Desc: 2023 TT FOREST RIVER

CHEROKEE GREY WOLF 23MKBL

Chassis #: 4X4TCKY29PK085838

Serial #: 4X4TCKY29PK085838

Mileage: 0

Licence:

Invoice #:

Date In: 07 NOV 22

Promised: 31 DEC 22

Date Sched:

Completed: 30 NOV 22

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*69480 on 02 DEC 22

Estimate amount was 0.00

PDI - NEW TRAVEL TRAILER

CAUSE: pdi new unit

CORRECTION: pdi new unit

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Internal

COMPLAINT: Transferred to BAS*69480 on 02 DEC 22

Estimate amount was 0.00

SOUTSIDE SHOWER DOOR NOT LOCKING

CAUSE: shower door latch needed lubed and adjusted

CORRECTION: shower door latch needed lubed and adjusted

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: BLIND BY SOFA RUBBING

CAUSE: blinds by sofa was rubbing on curtain mounts. moved curatin mounts and filled in old holes



Customer #:
1000



CORRECTION: blinds by sofa was rubbing on curtain mounts. moved curtain mounts and filled in old holes

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	7.50
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00

Subtotal for Job #2: 7.50

Job #WINTER - Internal

Transferred to BAS*69480 on 02 DEC 22

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	RAB	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #3 - Warranty

COMPLAINT: BOTTOM SLIDE SEAL IS HANGING LOOSE

CAUSE: bottom slide seal hanging lose

CORRECTION: reattached bottom slide seal

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	30.00

Subtotal for Job #3: 30.00

Job #4 - Warranty

COMPLAINT: KITCHEN SINK NOT SEALED

CAUSE: kitchen sink was never sealed and needs sealed

CORRECTION: kitchen sink was never sealed and needs sealed

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	15.00

Subtotal for Job #4: 15.00

Parts Total: 0.00
Labour Total: 52.50
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 52.50

W/O: 69215
Promised Date:
31 DEC 22



Customer #:
1000



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 05 Dec 2022

W/O: 69215
Promised Date:
31 DEC 22



Customer #:
1000



Customer Work
Order

