



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 69320

### CUSTOMER WORK ORDER

WO #: 69320 (Appointment Date: 15 NOV 2022 - Time: 07:00am)

Customer: 28425 - AMES, EDWARD M. Stock #: 11160  
- 816-309-5609 Stock Desc: 2022 TT COACHMEN  
Tag: SPIRIT 1943RB  
Author: PH Chassis #: 5ZT2SBHB2NS043804  
Location: 1201 CHECK WORK Serial #: 5ZT2SBHB2NS043804  
Mileage: 0  
Licence:

Invoice #:  
Date In: 14 NOV 22  
Promised:  
Date Sched:  
Completed: 28 NOV 22  
Warr. Date: 29 APR 22



#### Job #1 - Warranty

COMPLAINT: WOOD BELOW REFER DAMAGED. DRAIN HOSE MIGHT OF CLOGGED

CORRECTION: CHECK AND FOUND DRAIN OPEN, 12 vdc REFERS DO NOT DRAIN TO OUTSIDE, THEY DRAIN TO PAN BY COMPRESSER AND EVAPERAT, IF UNIT IS TILTED NOSE DOWN IT WILL RUN INSIDE OF UNIT, TAKE PICA AND TURN IN PARTS ODER TO REBUILD CABNET FACE FRAME, REFER WILL HAVE TO BE PULLED TO REBUILD CABNET FRAME

#### Labor

| Code | Description                 | Mechanic | Total  |
|------|-----------------------------|----------|--------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | BB       | 600.00 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | JP       | 0.00   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | JP       | 0.00   |

#### Parts

| Part # | Description  | Qty  | Price | Total |
|--------|--|------|-------|-------|
| 7550   | STILE, 3/4" X 1-1/2" X 8' RAD VW LC<br>MONTICOLA MAPLE | 8.00 | 0.90  | 7.20  |
| 7551   | STILE, 3/4" X 1-1/2" X 8' SQ VW LC<br>MONTICOLA MAPL   | 8.00 | 0.81  | 6.48  |
| 7552   | STILE, 3/4" X 2" X 8' RAD VW LC<br>MONTICOLA MAPLE     | 8.00 | 1.12  | 8.96  |
| 7553   | STILE, 3/4" X 2" X 8' SQ VW LC<br>MONTICOLA MAPLE      | 8.00 | 0.98  | 7.84  |
| 7555   | STILE, 3/4" X 4" X 8' SQ VW LC<br>MONTICOLA MAPLE      | 8.00 | 1.83  | 14.64 |
| 7556   | STILE, 3/4" X 5" X 8' SQ VW LC<br>MONTICOLA MAPLE      | 8.00 | 2.28  | 18.24 |

#### Other Services

| Code | Description   | Qty  | Price  | Total  |
|------|---------------|------|--------|--------|
| SS   | SHOP SUPPLIES | 1.00 | 0.00   | 0.00   |
| FRT  | UPS-STILES    | 1.00 | 189.56 | 189.56 |

**Subtotal for Job #1: 852.92**

#### Job #2 - Warranty

COMPLAINT: BLACK TANK FLUSH HOSE THAT RUNS UNDER BATHROOM SINK IS KINKED AND CAUSED A WATER PROBLEM

CORRECTION: GET IN BATHROOM CABNET REMOVE ACSESS PANEL AND FOUND BLACK TANK FLUSHER LINE TOO LONG AND CRIMPING OFF, REMOVEFLUSHER INLET AND CUT LINE BACK BEHIND CRIMP, REMOUNT END AND WATER TEST, MOUNT INLET AND CAP SEAL

#### Labor

Customer #:  
28425



Code Description  
Z990 MISC LABOUR CODE (EXTERNAL)

Mechanic Total  
JP 45.00

**Subtotal for Job #2: 45.00**

Parts Total: 63.36  
Labour Total: 645.00  
Sublet Total: 0.00  
Extras Total: 189.56  
**WORK ORDER TOTAL: 897.92**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 28 Nov 2022

W/O: 693320



Customer #:  
28425

