

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69326
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 11817 - BRYAN E. MEYER
Address: 11488 S 150 E HAUBSTADT, IN

47639

Phone: 812-664-5566

Stock Number: 10468 - 2022 SPIRIT 1943RB 5ZT2SBHB4NS044095

VIN: 5ZT2SBHB4NS044095 HIN: SER#: 5ZT2SBHB4NS044095

Mileage: 0 Work Order Comp: 17 NOV 22

Auth. No: Dealer #:

Warr. Date: 26 MAY 22 Work Order Date: 14 NOV 22 Inv #: 385453

WO # Job # Description JOB INFORMATION

69326 1 22E-055 LIPPERT AWNING RECALL
AWNING DOES NOT FALL UNDER RECALL. INSPECTED SEAMS. SEAMS LOOK
GOOD AND PASS PUSH TEST
NO CORRECTION

69326 2 THE LEVEL INDICATOR ON THE FRESH WATER TANK IS NOT REGISTERING.
NOTE: UNIT IS WINTERIZED
PULLED UNIT INTO SHOP. REMOVED TANK SUPPORTS ON ONE SIDE. REMOVED
OTHER BOLTS TO PULL DOWN UNDERBELLY. ALL WIRES AND CONNECTIONS
LOOK GOOD. WENT TO FILL TANK AND WATER STARTED TO BACKFEED
THROUGH THE FILL LINE. NOTICED THE FILL LINE RUNS BELOW THE
FITTING ON THE TANK AND THE OVERFLOW LINE IS IN THE WAY OF THE
FILL LINE.
TOOK A HEAT GUN AND HEATED UP FILL LINE TO HELP REMOVED FROM
FITTING. CUT OFF ABOUT 2/12 INCHES OFF THE FILL LINE AND
RESECURED TO TANK FITTING. POSITIONED OVERFLOW LINE SO I COULD
LEVEL OUT FILL LINE HOSE. SECURED TANK BRACKETS TO FRAME. FILLED
FRESH TANK ALL THE WAY FULL. ALL SENSORS ARE READING AS THEY
SHOULD. INSTALLED THE REMANING BOLTS FOR UNDERBELLY. DRAINED
FRESH TANK. CLEANED UP MESS.

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 1 MISC LABOUR CODE (EXTERNAL) 0.30 150.00 45.00
Z990 2 MISC LABOUR CODE (EXTERNAL) 0.50 150.00 75.00

Claim : 69326

Lab Code Job# Description LABOUR Hrs Rate Total

Excode Job# Description EXTRAS Qty Price Total

SS 2 SHOP SUPPLIES 1.00 0.00 0.00

Parts Total: 0.00
Labour Total: 120.00
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 120.00

Customer Signature: _____

Date: _____