



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 69340  
Promised Date: 30 NOV 22

### CUSTOMER WORK ORDER

WO #: 69340 (Appointment Date: 15 NOV 2022 - Time: 07:00am)

Customer: 52459 - MCKENDREE,  
KENNETH D. -

Tag:

Author: BH

Location: 1122 BH TO CLOSE

Stock #: 11207

Stock Desc: (11207) 2022 KEYSTONE  
SPRINGDALE 1740RK

Chassis #: 4YDTSGG19NW109167

Serial #: 4YDTSGG19NW109167

Mileage:

Licence:

Invoice #:

Date In: 15 NOV 22

Promised: 30 NOV 22

Date Sched:

Completed: 22 NOV 22

Warr. Date: 16 MAY 22

#### Job #LIPPERT - External

Transferred to BAS\*69341 on 15 NOV 22

Estimate amount was 0.00

#22-434 LIPPERT AWNING RECALL (INSPECTION)

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

**Subtotal for Job #LIPPERT: 0.00**

#### Job #2 - Warranty

COMPLAINT: CHECK WATER HEATER NOT WORKING ON GAS RIGHT WILL COME ON 30 SECS AND SHUTS OFF AND ABOUT 5 MINS LATER IS COMES BACK ON... BUT WHEN ON CITY IT WORKS IT GETS TOO HOT AND STARTS BLOWING OUT THE VALVE

CORRECTION: filled water heater with water and check temp it was 165 degrees,that it to hot,replaced thermostat and ecm,filled with water again and it was 150 and no water was coming out of pop off valve.

#### Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	0.00
Z990	MISCELLANEOUS REPAIR	DGH	33.00
Z990	MISCELLANEOUS REPAIR	DGH	42.00

#### Parts

Part #	Description	Qty	Price	Total
91447	ATWOOD ECO & TSTAT	1.00	16.08	16.08

**Subtotal for Job #2: 91.08**

#### Job #3 - Warranty

COMPLAINT: THE MURPHY BED FALLS IT IS SITTING ON THE COUNTER

CORRECTION: HAD TO GET NEW SCREWS TO MOUNT LATCH,REINSTALLED LATCH AND DRILLED NEW HOLE FOR LATCH TO CATCH.

#### Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	30.00

Customer #: 52459



Subtotal for Job #3: 30.00

**Job #4 - Warranty**

COMPLAINT: FRONT BPASSANGER UNDERLINER THE UNDER BELLY IS BUNCHED UP IN THE FRAME

CORRECTION: CUT EXCESS UNDERBELLY OFF AND TOOK SCREWS OUT TO REINSTALL UNDERPENING THE RIGHT WAY,REINSTALLED SCREWS AND PUT UNDERBELLY TAPE ON FOR REENFORCEMENT.

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	60.00

Subtotal for Job #4: 60.00

**Job #5 - Warranty**

COMPLAINT: ONE OF THE STEP LEGS ON THE FOLD OUT STAIRS IS STUCK CHECK AND ADVISE

CORRECTION: TOOK OUT LEG AND SANDED DOWN,TO MUCH PAINT ON LEG IT WAS BINDING UP,NOW IT WORKS GREAT.

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	15.00

Subtotal for Job #5: 15.00

**Job #6 - Internal**

COMPLAINT: FRIDGE DOES NOT SWITCH FROM ELE TO GAS

CORRECTION: NOTHING WRONG WITH FRIG,IT SWITCHES OVER LIKE IT IS SUPPOSE TO,MAYBE CUSTOMER IS EXPECTING IT TO LIGHT ON GAS WHEN IT IS ALREDY COLD FROM ELECTRIC,IN WHICH IT WONT UNTIL TEMP COMES DOWN AND THEN IT LIGHTS ON GAS,

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	N/C

Subtotal for Job #6: 0.00

Parts Total: 16.08  
 Labour Total: 180.00  
 Sublet Total: 0.00  
 Extras Total: 0.00

**WORK ORDER TOTAL: 196.08**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 22 Nov 2022

W/O: 69340  
Promised Date:  
30 NOV 22



Customer #:  
52459

