



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69347



CUSTOMER WORK ORDER

WO #: 69347 (Appointment Date: 16 NOV 2022 - Time: 07:00am)

Customer: 52897 - BRETZ, TIMOTHY
S. - 270-617-8080

Tag:

Author: BH

Location: 1130 CHECK PARTS

Stock #: 10827

Stock Desc: 2022 TT FOREST RIVER
CHEROKEE 274WK

Chassis #: 4X4TCKC24NX158511

Serial #: 4X4TCKC24NX158511

Mileage: 0

Licence:

Invoice #: 385754

Date In: 16 NOV 22

Promised:

Date Sched:

Completed: 29 NOV 22

Warr. Date: 29 JUL 22

Job #1 - Warranty

COMPLAINT: SOME OUTLETS DONT WORK THE GCFI OUTLETS DO NOT WORK

CAUSE: THE GFCI OUTLET ON THE CELING WAS BAD. INSTALLED NEW ONE AND TESTED AND WORKED JUST FINE. PUT OLD ONE ON WARANTY SHELF

CORRECTION: THE GFCI OUTLET ON THE CELING WAS BAD. INSTALLED NEW ONE AND TESTED AND WORKED JUST FINE. PUT OLD ONE ON WARANTY SHELF

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	45.00

Parts

Part #	Description	Qty	Price	Total
72-7218	GFI RECEPTACLE - BLACK	1.00	20.23	20.23

Subtotal for Job #1: 65.23

Job #2 - Warranty

COMPLAINT: KITCHEN FAUCET LEAKS AT THE BASE

CAUSE: LEAKING AT THE BASE NEED TO INSTALL NEW

CORRECTION: NEED TO INSTALL NEW FAUCET

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	22.50
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	19.50
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	33.00

Parts

Part #	Description	Qty	Price	Total
F100127527	FAUCET, KITCHEN SPRING FAUCET - MATTE BLACK (796511) / 2020	1.00	95.78	95.78

Other Services

Code	Description	Qty	Price	Total
FRT	FRT FAUCET AND LIGHTS	1.00	15.96	15.96

Subtotal for Job #2: 186.74

Customer #:
52897



**Job #3 - Warranty**

COMPLAINT: FLOOR AT THE ISLAND IS SQUEEKY WHEN WALKING BY IT

CAUSE: floor at island at register vent was squeaking. put some insulation on the vent and stopped squeaking

CORRECTION: floor at island at register vent was squeaking. put some insulation on the vent and stopped squeaking

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	15.00

Subtotal for Job #3: 15.00**Job #WINTER - External**

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: WINTERIZE CUSTOMER UNIT TOOK 2 GALS

CORRECTION: WINTERIZE CUSTOMER UNIT TOOK 2 GALS

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00**Job #4 - Warranty**COMPLAINT: BLUE ACCENT LIGHTS ON BOTH SLIDES ARE
HANGING DOWNCAUSE: FOUND LIGHTS ARE FALLING
DOWN THE STICKY IS MISSINGCORRECTION: NEED TO
REPLACE THE LIGHTS ABOVE THE SLIDE ROOMS**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	52.50
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	7.50

Parts

Part #	Description	Qty	Price	Total
20X68931A	LED LIGHT STRIP, 144" BLUE LIGHTS	2.00	17.84	35.68

Subtotal for Job #4: 95.68

W/O: 69347



Customer #:
52897



Parts Total:	151.69
Labour Total:	195.00
Sublet Total:	0.00
Extras Total:	15.96

WORK ORDER TOTAL: 362.65

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 29 Nov 2022

Customer Work Order

