

e-Authorization

1/19/20
03:12:56

Authorization number PA03313613 Reference no: 69388 Status: Approved Approved by parke Approved date 1/13/2023
 RVing Name Address Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDFCGR29N2504733 10/13/2022
 600 E Baseline Rd
 Evansville, IN 47725

Root operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3101016B Cabinet Door - Hi	0.00	0.30	0.10		1	0.10	Complaint:OUTSIDE KITCHEN CABINET LEFT THE HINDGE IS COMING OFF AND NEEDS TO BE REINSTALLED Cause:FOUND SCREWS CAME OUT Correction:INSTALLED SCREWS IN THE HINGE KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
2	1207525B Step - Replace	0.00	1.00	0.50		1	0.50	Complaint:ON THE STEPS TO WALK TO THE BEDROOM THE WOOD IS COMING OFF NEED TO REPLACE Cause:FOUND WOOD PANEL COMING OFF Correction:HAVE TO PULL OLD STEP OFF AND REPLACE WITH NEW KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
3	3102108B Countertop - Kitch	0.00	4.00			1	2.00	Complaint:THE KITCHEN COUNTER TOP NEAR THE ENTRY DOOR IS STARTING TO COME OFF AND IS NIKD Cause:INSTALL ISSUE Correction:WILL HAVE TO REMOVE THE COUNTER TOP AND KITCHEN SINK TO FIX KRV - No defect presented
4	5104219A Receptacle - 12V	0.00	0.40			1	0.20	Complaint:ABOVE THE CABINET IN THE REAR BATHROOM THERE IS A LOT OF WIRES ABOVE IT NEED TO BE TRIMED DOWN AND TIED UP Cause:FOUND WIRES HANGING OFF THE CABINET Correction:CUT OUT WIRES AND SHORTENED THEM AND RECONNECTED AND SECURED ON TOP OF CABINET. KRV - The issue submitted is not considered a warranty defect in materials or workmanship.
5	2302816B Garage Door, Lar	0.00	0.70	0.50		1	0.30	Complaint:THE SEAL IN THE OUTSIDE KITCHEN IS COMING OFF Cause:THE SEAL AROUND THE OUTSIDE KITCHEN DOOR WAS COMING OFF AND STUCK TO THE DOOR I TURNED IN REQUEST TO CRAIG.

paper claims only use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

e-Authorization

1/19/20
03:12:56 P

In Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
----------------------	-------------	--------	-----------	-------------------	-----------------	-----	---------------	--------------------------------

3-Authorization number PA03313613				1.10				Correction:NEED TO REPLACE THE SEAL WITH NEW KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual. VCB
-----------------------------------	--	--	--	------	--	--	--	--

For paper claims ~~only~~ use one pre-authorization number per warranty claim for
 please a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the