



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69388
Promised Date:
24 JAN 23



Customer #:
23199



CUSTOMER WORK ORDER

WO #: 69388

Customer: 23199 - HOFFMAN,
JOSEPH - 812-604-1758

Tag:

Author: BH

Location: 0120 CHECK TO SEE IF
THEY GAVE MORE TIME

Stock #: P4733

Stock Desc: 2022 5W KEYSTONE
COUGAR HALF-TON 32BHS

Chassis #: 4YDFCGR29N2504733

Serial #: 4YDFCGR29N2504733

Mileage:

Licence:

Invoice #:

Date In: 19 NOV 22

Promised: 31 JAN 23

Date Sched:

Completed: 19 JAN 23

Warr. Date: 07 JAN 23

Job #1 - Warranty

COMPLAINT: OUTSIDE KITCHEN CABINET LEFT THE HINGE IS COMING OFF AND NEEDS TO BE REINSTALLED

CAUSE: INSTALLED SCREWS IN THE HINGE WHILE DOING SO I NOTICED THE SEAL AROUND THE OUTSIDE KITCHEN DOOR WAS COMING OFF AND STUCK TO THE DOOR I TURNED IN REQUEST TO CRAIG.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR		0.00
Z990	MISCELLANEOUS REPAIR	BRM	15.00

Subtotal for Job #1: 15.00

Job #2 - Warranty

COMPLAINT: ON THE STEPS TO WALK TO THE BEDROOM THE WOOD IS COMING OFF NEED TO REPLACE

CAUSE: TURNED IN PARTS REQUEST TO CRAIG

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	22.50
Z990	MISCELLANEOUS REPAIR	BRM	52.50
Z990	MISCELLANEOUS REPAIR		0.00

Parts

Part #	Description	Qty	Price	Total
658977	MDF - Step - Tread - 1 1/4" x 11 1/2" x 28 1/2" - Pressed - C2 - Round Over - w/Buildup - Velvet Wenge	1.00	42.39	42.39

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-STEP	1.00	27.86	27.86

Subtotal for Job #2: 145.25

Job #3 - Internal

COMPLAINT: THE KITCHEN COUNTER TOP NEAR THE ENTY DOOR IS STARTING TO COME OFF AND IS NIKD

CAUSE: TURNED IN SHEET FOR BEN TO GET APPROVAL



W/O: 69388
Promised Date:
31 JAN 23



Customer #:
23199



Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR		N/C
Z990	MISCELLANEOUS REPAIR	BRM	N/C
Subtotal for Job #3:			0.00

Job #4 - Internal

COMPLAINT: ABOVE THE CABINET IN THE REAR BATHROOM THERE IS A LOT OF WIRES ABOVE IT NEED TO BE TRIMED DOWN AND TIED UP

CORRECTION: CUT OUT WIRES AND SHORTENED THEM AND RECONNECTED AND SECURED ON TOP OF CABINET.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	N/C
Subtotal for Job #4:			0.00

Job #5 - Warranty

COMPLAINT: THE SEAL IN THE OUTSIDE KITCHEN IS COMING OFF

CAUSE: THE SEAL AROUND TO OUTDOOR KITCHEN DOOR IS COMING OFF.

CORRECTION: Original bulb seal around outside kitchen door came off at top and had double face tape stuck to compartment frame and top of door frame. Had to use heat gun and glue remover to clean off old stuuf to allow new bulb seal to be installed. Installed new bulb seal all around flange of opening.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	0.00
Z990	MISCELLANEOUS REPAIR	DKM	30.00
Z990	MISCELLANEOUS REPAIR	DKM	45.00

Parts Part #	Description	Qty	Price	Total
219210	Seal - D Seal - EPDM - .57" x .44" - w 1/2" PSA Tape - Automotive Grade - 500'/Bx	20.00	0.37	7.40

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SEAL	1.00	15.99	15.99
Subtotal for Job #5:				98.39

Parts Total:	49.79
Labour Total:	165.00
Sublet Total:	0.00
Extras Total:	43.85
WORK ORDER TOTAL:	258.64

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 19 Jan 2023

