

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD
EVANSVILLE, IN 47725
USA

CLAIM STATUS Authorized
CLAIM 1341970
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 4X4TCKZ21PX160923
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 017 / 017A
ITEM # ACKT243TR
DEALER RO # 69425
CLAIM START DATE 12/02/2022
CLAIM END DATE 01/01/1900

Labor rate: \$150.00
OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 Operation Code 30-103-24-00-001125 Operational Description Linoleum - Interior/Flooring/Repair/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-12-02 16:50:31 :: THE VINEL FLOOR HAS A CUT IN IT (NOD) work press and seal under vinel at cut roll flat and put anweight on top to hold in place
Model # Dlr Sub Hrs 1.00 Sub Labor Amt \$150.00
Serial # Appr Hrs 1.00 Appr Labor Amt \$150.00

Notes

Labor

Line# 2 Operation Code 30-307-01-00-001183 Operational Description Fireplace - Interior/Fireplace/Replace/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-12-02 16:51:49 :: NO POWER AT THE FIRE PLACE pull fireplace out of cabnet and test for power, have 120vac to recepical, run power cord to fire place and it will not work, turn in PO for new fire place, remount fireplace pull fireplace out of cabnet and test for power, have 120vac to recepical, run power cord to fire place and it will not work, turn in PO for new fire place, remount fireplace so unit can be put out on sales lot
Model # IF-1330TCL Dlr Sub Hrs 0.30 Sub Labor Amt \$45.00
Serial # NA Appr Hrs 0.30 Appr Labor Amt \$45.00

Notes

please attach picture of the cut cord before sending claim to processing

Submitted

Labor Amt \$195.00
Parts & Freight \$0.00
Total \$195.00

Approved

Labor Amt \$195.00
Parts & Freight \$0.00
Total \$195.00

DEALER DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.